

Florida

Attorney General
Pam Bondi



**2018 Holiday
Consumer Protection
Guide**

Season's Greetings Floridians,

Once again, as the holiday season approaches, my Office is pleased to provide this 2018 Holiday Consumer Protection Guide, a compilation of consumer tips and product safety information assembled to help you enjoy a safe and satisfying shopping experience.

This guide offers tips on making online purchases and avoiding charity scams. Also included is a list of items recalled by the U.S. Consumer Products Safety Commission in the past year, specifically focusing on children's toys, common household goods and items that pose particular risk to kids and teens. These products have been recalled by their manufacturers because of safety and health concerns and include toys, clothing, furniture, sporting goods and other products that may be unsafe for children. I urge you to review this list for items that may need to be immediately removed from your home. Please also keep this guide handy as you purchase and receive gifts this holiday season.

If you have questions regarding any of the tips discussed in this guide, feel free to contact my Citizens Services hotline at 1-866-9-NO-SCAM (1-866-966-7226), or visit our website at www.MyFloridaLegal.com. You can find more information on recalls and a comprehensive list of recalled items year-round at the U.S. Consumer Product Safety Commission's website at www.CPSC.gov/en/Recalls.

Have a safe and happy holiday season!

Sincerely,

A handwritten signature in black ink that reads "Pam Bondi". The signature is written in a cursive, flowing style.

Pam Bondi

Florida Attorney General

Table of Contents

Holiday Shopping Tips	4
Charity Scams	5
Product Recalls	6
Baby and Toddler Goods	8
Children’s Clothing & Accessories.....	16
Furniture.....	25
Household Goods.....	37
Sporting Goods and Recreational Vehicles.....	78
Toys.....	94
Other Resources	104

Holiday Shopping Tips

The holiday season is a time to be particularly mindful of ways your purchases can cost you more than expected. Below are some tips to help you keep your money safe while getting the most out of it:

- ❖ When shopping online it is often wise to pay with a credit card instead of a debit card, if possible. Both payment methods allow you to dispute a charge if the merchandise never arrives or is different from what was ordered. However, with a debit card, the purchase is already deducted from your bank account and it may take days or weeks for your bank to reverse the charge.
- ❖ When ordering online, ensure that the web browser has a secure connection before inputting or submitting payment information. In the address bar, a padlock should appear if your session is secure.
- ❖ Know that some debit and credit card providers offer one-time card numbers to be used for online transactions to further protect their cardholders. Log in to your account or contact your card provider to see if it offers this service.
- ❖ Remember that when shopping online there are often additional costs such as shipping and handling. Be sure to account for such additional charges when comparing prices across retailers or when making the choice between an online purchase or an in-store purchase.
- ❖ Keep your receipts and be sure you understand retailers' return policies and periods so you can return any unwanted item(s) for a full refund.
- ❖ Some retailers offer layaway plans or other payment options to allow shoppers to pay for items in installments or at a later date. Before agreeing to such a plan, be sure to ask whether the retailer charges a fee for its program and whether payments and any fees are refundable if the purchase is canceled or the product is returned.
- ❖ When purchasing gift cards, know whether there is an additional activation fee, and provide the activation receipt to the recipient. Additionally, consider the retailer's financial situation before buying a gift card. If the retailer closes or declares bankruptcy, the recipient may not be able to enjoy the card's value.

Charitable Giving Tips

While the holiday season often puts many in a kind and charitable mood, be on the lookout for scam artists who may seek to take advantage of that spirit of giving. Below are tips to help ensure that your dollars do the most good this season:

- ❖ Before donating, ensure that the charity is legitimate and eligible to solicit in the State of Florida. Check to see if the charity is registered with the Florida Department of Agriculture and Consumer Services at www.800HelpFLA.com or by calling 1-800-HELP-FLA (1-800-435-7352).
- ❖ Additionally, be sure you understand how much of a donation will actually go toward the work of the charity, as opposed to administrative and fundraising expenses. To learn about a registered charity's spending, again visit www.800HelpFLA.com and click on "Check-A-Charity" to ensure that its spending aligns with your values.
- ❖ Do your homework and review any charitable solicitation carefully. Search online to see what others may be saying about the charity. You may also contact the Better Business Bureau's Wise Giving Alliance at www.Give.org or Charity Navigator at www.CharityNavigator.org to determine whether the charity has any complaints against them.
- ❖ Do not give your credit card number or bank account information to someone who has called or emailed you unsolicited. If you are interested in donating to a charity that has contacted you, ask them to mail you information about the charity and a pledge form. Legitimate charities should have no problem with this request.
- ❖ Watch out for similar sounding charities. It is not unusual for scam artists to choose names that sound like the names of legitimate, widely-known charities.
- ❖ Know the difference between tax exempt and tax deductible. An organization that is tax exempt does not have to pay taxes, but this does not necessarily mean that a contribution you have made to it is tax deductible. To check whether an organization is eligible to receive tax-deductible contributions, visit <https://apps.irs.gov/app/eos/>.

Product Recalls

With so many purchases made in anticipation of and throughout the holidays, it is more important than ever to be vigilant about the safety of the products brought into your home. What follows is a compilation of 2017-2018 U.S. product recalls in an easy-to-use guide that I hope you will consult as you give and receive items this holiday season.

The guide reproduces details about recalled toys, baby items, sporting and recreational goods, furniture, and household products that are either designed for or pose a particular risk to children and teenagers. These items were among the nearly 300 products recalled by the U.S. Consumer Product Safety Commission between November 1, 2017, and November 15, 2018. For more information regarding these products or for a comprehensive list of all product recalls, please visit www.CPSC.gov.

Dangerous and defective products are the subject of recalls every year. When a product is recalled, the law requires manufacturers and retailers to remove the products from their shelves. However, products subject to recall do sometimes slip by undetected and may remain on shelves. Others may have been purchased before the recall was even issued. Many products may also continue to be offered for sale online well after the recall through various online reseller websites. Therefore, it is always important to do your research to make sure that the products you are buying or bringing into your home are safe and free of defect.

Taking a few minutes now to peruse this collection of recalled items will ensure a safer and more enjoyable holiday for you and yours.



Baby and Toddler Products



LILLEbaby Active Series Baby Carriers

Hazard: The sliding chest-clip strap can detach from the shoulder strap, posing a fall hazard to the child in the carrier.

This recall involves LÍLLÉbaby Active series baby carriers. These carriers can be worn by the caregiver with the baby strapped into the front or back position. The recalled carriers are the Active Series-Pro 6 in 1 in Space Dye Cobalt and Space Dye Grey and the Active All Seasons in Slate. Each carrier has a yellow colored tag on the front neck support, outside of the carrier and on the back, chest clip pad, both of which have “LÍLLÉ” printed in black lettering and “baby” printed in white lettering on the label. These carriers were sold online at LILLEbaby.com and Amazon.com for about \$160.



Remedy: Consumers should immediately stop using the recalled carriers and contact LÍLLÉbaby to receive a free replacement baby carrier and a full refund.

Eddie Bauer Infant Carriers

Hazard: The buckles on the infant carriers can break, posing a fall hazard to children.

This recall involves Gold Inc.’s Eddie Bauer fabric infant carriers. They are worn by the parent or caregiver with the baby strapped into the front. The recalled carriers are black with “Eddie Bauer” and “First Adventure” printed in gray lettering on the front, outside of the carrier. These carriers were sold at Target stores nationwide and online for about \$70.



Remedy: Consumers should immediately stop using the recalled carriers and contact Gold Inc. to verify that the product is subject to this recall. Once the product is verified, consumers will receive replacement products of comparable value or a full refund.

Tubeez Baby Bath Seats

Hazard: The bath support seat fails to meet the federal safety standard including the requirements for stability. The bath seat can tip over or an infant can slip underneath the front support, posing a drowning hazard.



This recall involves the Tubeez Baby Bath Support Seats. The baby bath support is a rigid plastic seat attached to a foam mat for use in the bathtub. The foam mat is either blue, with the model code B9150BL, or gray, with the model code B9150GY, and features multiple suction cups on the underside. The affected seats have the date codes 1251-0916-enj-nacn or 1434-0617-enj-nacn printed on the underside of the mat. These seats were sold at Bealls Outlets nationwide for about \$40.

Remedy: Consumers should immediately stop using the recalled bath support seats and contact Abond Group for a full refund.

Jane Muum Strollers

Hazard: The recalled strollers violate the federal Stroller and Carriage standard. An infant can pass through the opening between the stroller armrest and the seat bottom and his/her head and neck can become entrapped by the armrest, posing entrapment and strangulation hazards.



This recall involves the US model of Jané Muum strollers. The recalled strollers have a black frame, a reclining seat or hammock that is reversible and a hood. An insert is sold with the stroller for smaller babies. There is a basket for storage underneath the stroller seat. The recalled strollers were sold in: dark gray and black (S85), light grey and black (S49), blue and black (S46) and green and black (S47). “Muum by Jané” is printed on the front bottom frame. “Muum” is printed on the side frame and on the handle. “Jané”

and “Muum,” “Jané USA LLC,” “Muum US 5399US/S85” or “S47,” “S49,” “S46” are printed on a label on the leg of the stroller. These strollers were sold at retailers nationwide and online for between \$300 and \$450.

Remedy: Consumers should immediately stop using the recalled strollers and contact Jané for a free repair. The repair consists of a free replacement armrest. Consumers can continue using the recalled strollers if they remove the armrest and harness the child properly until they receive the replacement armrest.



Dr. Brown’s Lovey Pacifier and Teether Holders

Hazard: The snap can detach from the pacifier’s ribbon, posing a choking hazard for young children.

This recall involves Dr. Brown’s Lovey pacifier and teether holders. The holders were sold in eight styles: Giraffe, Zebra, Turtle, Reindeer (Special Holiday Edition), Frog (Special Holiday Edition), Spring Bunny (Special Holiday Edition), Deer and Bunny. Only holders with the following lot codes are included in this recall: RICH0615, RICH0715, RICH0815, RICH1215, RICH0516, RICH0616, RICH0716, RICH1116, RICH1016, RICH0916, RICH1216, RICH0317, RICH0417, RICH0517, RICH0617, RICH0717, RICH0817, and RICH0917. The lot codes are printed on the tag attached to the holder. Consumers can confirm lot codes included in the recall at www.drbrownsbaby.com/recall-lovey. These holders were sold by retailers nationwide and online for about \$10.



Remedy: Consumer should immediately take the recalled holders away from young children and contact Handi-Craft for further instructions to receive a replacement product or comparable merchandise of equal or lesser value.

Babynest Crib Bumpers

Hazard: The strings on the crib bumper exceed a safe length, posing a strangulation hazard to babies.

This recall involves Babynest crib bumpers used in Babybay bedside sleeper cribs that attach to adult size beds. The recalled bumpers measure 60 inches long by 9.5 inches wide and were sold in seven colors; yellow, brown, green, blue, pink, white, gray with white stars, white with gray stars, gray with white polka dots, white with gray polka dots and white with blue stars. Affected SKU numbers include 167805, 167806, 167807, 167808, 167810, 167811, 167814, 167815, 167816, 167817, and 167820. These crib bumpers were sold exclusively online at babybay.us for about \$45 to \$65.



Remedy: Consumers should immediately stop using the recalled crib bumpers and contact Babybay for a full refund.

Graco 6-in-1 Highchairs

Hazard: The highchair's rear legs can pivot out of position making the chair unstable and posing a fall hazard to a child in the highchair.



This recall involves Graco Table2Table 6-in-1 highchairs with model number 1969721. The 6-in-1 highchairs convert to six different modes, including a traditional highchair, a booster seat and toddler chair and table. The highchair's cushion is white with gold and gray polka dots. The model number is printed on a label on the underside of the toddler seat and on a label on the back of the booster seat. These highchairs were sold at Walmart stores nationwide and online at Walmart.com for about \$100

Remedy: Consumers should immediately stop using the recalled highchairs and contact Graco for a free repair kit.

Multipro Baby Cradle N Swings

Hazard: The bassinets fail to meet the mandatory federal safety standard for bassinets and cradles, posing fall and entrapment hazards to babies.

This recall involves Multipro bassinets, an Indian style baby cradle. It has a swing framework with a pair of metal

legs on the ends of the middle rod. The Cradle N Swing is designed to swing the child back and forth in a bassinet. The bassinet is made of polka dot fabric with a mesh opening on the side. The bassinet portion attaches to a plastic frame base and is sold in a variety of colors. Multipro is written on the outside of the storage bag.



Remedy: Consumers should immediately stop using the Multipro Baby Cradle N Swing, disassemble it and throw it away. Consumers who purchased the product on Amazon.com have been automatically issued a gift card refund for the full purchase price.

Tuo Convertible High Chairs

Hazard: The front legs on the highchair can detach from the seat, posing fall and injury hazards to children.



This recall involves the charcoal colored Tuo convertible high chair, which can be converted into a toddler chair. The style numbers are 304200 and 304200CN with a date code found on the back of the chair as follows: HH10/2016, HH11/2016, HH3/2017 and HH4/2017. The highchairs have a reversible seat pad, removable tray, 5-point harness, beechwood footrest and legs. These chair were sold at retailers nationwide and online for about \$160.

Remedy: Consumers should immediately stop using the recalled high chairs and contact Skip Hop for a free replacement.

Vtech Lights & Lullabies Travel Mobiles

Hazard: The clamp attaching the mobile to the crib rail can break causing the mobile to fall, posing an injury hazard to an infant in the crib.

This recall involves VTech Lights & Lullabies Travel mobiles. The recalled mobiles were sold in blue and pink. The model numbers are 80-503000 (blue) and 80-503050 (pink). The mobile measures 5 inches wide by 15.8 inches tall. The model numbers are printed on the battery compartment door. These mobiles were sold in stores and online for about \$25.



Remedy: Consumers should immediately stop using the recalled mobiles and contact Vtech for a full refund or a replacement product.

SquattyPottymus Toilet Step Stool

Hazard: The top removable step on the recalled children's toilet step stools can detach while a child is standing on it, posing injury and fall hazards.

This recall involves the SquattyPottymus children's toilet step stools used to assist a child in reaching a toilet seat. The plastic step stools measure about 15.8 by 16.8 by 10 inches and were sold individually or as a part of a set, which included a toilet seat and decorative stickers. The step stool is designed to look like a gray hippopotamus with blue or purple eyes. It has a height-adjusting aqua blue hat top step and cut-outs that function as handles on each side. These step stools were sold online for about \$50.



Remedy: Consumers should immediately stop using the children's toilet step stools until they remove the hat. Consumers should contact Squatty Potty for instructions on returning the hat portion of the stool, free of cost, for a \$10 refund.

Vornado Cribside Space Heaters

Hazard: A broken motor mount can allow the electric heating element to come in contact with the interior plastic materials and ignite, posing fire and burn hazards.

This recall involves Vornado Sunny CS (cribside) model EH1-0090 electric space heaters. They were sold in white with an accent of melon and gray colors. The controls are mounted in a soft touch panel on the top of the unit with a multi-color display in the center of the control panel. “Vornadobaby” is printed on the side of the heater. The model/type “SUNNY CS EH1-0090” and serial number are printed on a silver decal on the bottom of the unit under the elastic cord wrap. The recalled heaters have the numbers 1 and 7 as the fourth and fifth digits of the serial number (XXX17-XXXXXX). These heaters were sold for about \$100.



Remedy: Consumers should immediately stop using the recalled space heaters, unplug them and contact Vornado for instructions on how to receive a free replacement unit, including free shipping.



Children's Clothing and Accessories



H.I.S. Girl's Clothing & Jewelry Sets

Hazard: The necklace contains levels of lead that exceed the federal lead content ban.

This recall involves Self-Esteem brand girl's clothing sets with a gold leaf pendant necklace. The recalled clothing sets consists of three items: a short-sleeve teal top with cut-out shoulders, a navy legging with a teal floral print and a pendant necklace with an orange and teal center. The recalled clothing sets have style number PO#71160/LOT9 and a date of production of 10/2017 printed on a white label on the inside of the garment. These sets were sold in girl's sizes 4x-12x at Burlington and Shopko stores for about \$14.



Remedy: Consumers should immediately stop using the necklace from the recalled clothing sets and return it to the place of purchase for a full refund.

Fantasia (Cat & Jack) Slap Bracelets

Hazard: The slap bracelet's metal wristband can pierce the protective fabric around it and expose sharp edges, posing a laceration hazard.



This recall involves children's furry critter plush slap bracelets in panda, unicorn and heart designs. The recalled bracelets are made of a metal band covered with a protective fabric. These bracelets were sold exclusively at Target stores and online at Target.com for about \$5.

Remedy: Consumers should immediately stop using the recalled bracelets and contact Fantasia Accessories to receive a free replacement product.

Boy Scouts Neckerchief Slides

Hazard: The colored enamel on the neckerchief slides contains levels of lead that exceed the federal lead content ban.

This recall involves Boy Scouts of America's neckerchief slides. The brass neckerchief slides were sold in four styles: red wolf, green bear, orange lion and blue Webelos. "Made in China" and P.O.

number 200228276, 20023175, 200233281 or 200236630 are printed on a white label attached to the back of the neckerchief slide. These slides were Boy Scouts of America retail stores and authorized distributors nationwide for about \$6.



Remedy: Consumers should immediately stop using the recalled neckerchief slides, take them away from children and return them to any Boy Scouts of America retail store or distributor for a free replacement.

ED by Ellen DeGeneres Coveralls

Hazard: The bunny applique can detach, posing a choking hazard to young children.

This recall involves infant ED by Ellen DeGeneres coveralls with hat. The pink striped, two-piece, long-sleeve coveralls are 100% cotton. They have a kangaroo pocket and bunny-shaped applique on the left chest, a hat with pompom and snaps in the crotch.



Style ED01210 was sold in infant sizes 3M, 6M and 9M; and style ED13210 was sold in 12M, 18M and 24M. The style number and manufacture date code of August 2017 (08/2017) are printed on the inside garment tag located inside the seam of the garment. These coveralls were sold nationwide and online for about \$16.

Remedy: Consumers should immediately stop using the recalled coveralls and return them to the place of purchase for a full refund.

Okie Dokie Denim Shorts

Hazard: The patches on the shorts can detach, posing a choking hazard.

This recall involves Okie Dokie Denim Patches Shortie shorts. The shorts were sold in toddler sizes 2T through 5T. The item number 324-8191 and date

code 12/17 are printed on a white tag on the inside back seam of the shorts. These shorts were sold at JCPenney stores and online at JCPenney.com for about \$22.



Remedy: Consumers should immediately stop using the shorts and contact JCPenney for instructions on returning the shorts for a full refund in the form of a gift card.

Allura Children's Pajamas

Hazard: The children's pajamas fail to meet the flammability standard for sleepwear.

This recall involves two styles of children's sleepwear garments. The first garment is a 100% polyester fleece pajama pant with the brand name "Sweet N Sassy" on the waist label and hang tag. The style number is located on the back of the brand label at the center waist. The second garment is a 95% polyester and 5% spandex onesie with long-sleeves, a hood and front zipper with the brand name "Delia's Girl" at the neck label and hang tag. The style number is located on the back of the brand label at the neck. The garments were sold in children's sizes 4-6x and 7-16 in a variety of colors and prints. Recalled style numbers include: S65300, S65301, S65302, S65303, S67300, S67301, S67302, S67303, 65477, and 67477. These pajamas were sold at retailers nationwide and online for between \$8 and \$13.



Remedy: Consumers should immediately stop using the recalled sleepwear, take it away from children and contact Allura for a full refund.

Carter's 3-Piece Penguin Sets

Hazard: The cardigan's toggle button can detach, posing a choking hazard.

This recall involves Carter's 3-piece penguin cardigan sets. The recalled sets consist of a white embroidered penguin bodysuit, a grey cardigan with a hood and matching pair of pants. They were sold in sizes newborn to 24 months. Style number 127G596 and the UPC number are printed on the care tag sewn on the inside of the cardigan. The UPC numbers are 190795798203, 190795798166, 190795798173, 190795798180, 190795798135, 190795798142, 190795798159. These sets were sold in retailers nationwide and online for about \$40.



Remedy: Consumer should immediately take the recalled sets away from children, stop using them and contact Carter's for a full refund in the form of a gift card.

PAW PATROL Marshall Hat with Flashlight

Hazard: The batteries in the flashlight can overheat, posing burn and fire hazards.

The PAW PATROL Marshall hats are red with a yellow ribbon, black and white spotted dog ears and a black flash light attached to the side of the hat. The flashlight is included with the hat and they share the SKU number. Only flashlights with SKU 01292093 and date codes 1703RY01, 1603RY01, and 1503RY01 are involved in this recall. The SKU number and date codes are on the sewn in label under the ear on the hat.



Remedy: Consumers should immediately take the flashlight that was sold with the hat away from children, stop using it, remove the batteries and dispose of the flashlight and contact Spirit Halloween for a full refund.

Cat & Jack Girls' Studded Skinny Jeans

Hazard: The metal stars can detach, posing a laceration hazard.

This recall involves Cat & Jack Girls' Star Studded Skinny Jeans. The jeans were sold in sizes 4–18P and have metal stars on the front bottom portion of the legs. “Cat & Jack” and the words “Super Skinny” are printed on the inside waistband of the jeans. The hangtag attached to the jeans has one of the numbers in the sequence from 205-03-1377 to 205-03-1392 at the top of the tag. These jeans were sold at Target stores nationwide and at Target.com for about \$18.

Remedy: Consumers should immediately stop wearing the recalled jeans and return them to any Target store for a full refund.



PL Sleep Children's Sleepwear

Hazard: The sleepwear fails to meet the flammability standards for children's sleepwear.

This recall involves PL Sleep's children's 100 percent polyester nightgowns. The nightgown has a gray and white snowflake print on the long sleeves and a faux Sherpa fleece body with a red scarf, three black buttons and black belt decoration on the front. PL Sleep and model numbers 17FT62F561 and #101 are printed on a label sewn into the left inside seam.



Remedy: Consumers should immediately take the recalled nightgowns away from children and return the garments to the retailer where they were purchased or contact Lemur Group for instructions to get a full refund of the purchase price.

Tea Living Children’s Rompers

Hazard: The snaps near the collar can detach, posing a choking hazard to young children.

This recall involves two styles of children’s rompers sold in sizes 0-3 months and 18-24 months. They are Vermillion Painted OPP Floral Romper with style number 7F32500, and the Shocking Fuchsia Rose Romper with style number 7F32504. The Vermillion rompers are red with white floral print, and the Shocking Fuchsia are maroon with a pink floral print. The style number is printed on a tag sewn on the inside of the garment located in the waist area.



Remedy: Consumers should immediately take the recalled rompers away from children and contact Tea Living for a full refund.

Alstyle Infant Bodysuit

Hazard: The snaps at the crotch can detach, posing a choking hazard to young children.

This recall involves Alstyle infant bodysuits. The 100% cotton, short-sleeved bodysuits were sold in black, blue, pink and white. They have a lap shoulder construction with three-snap closure at the crotch. The bodysuits were sold in sizes 6M, 12M and 18M. “Alstyle” and “Made in Mexico” are printed on the neck label and “CAT – # – J” is printed on a white label sewn into the left inside seam. These were sold wholesale nationwide to designers and screen printers, so they likely have additional adornment or design.



Remedy: Consumers should immediately stop using the recalled bodysuits and contact Alstyle for instructions on returning the recalled bodysuits free of cost and to receive a \$10 Alstyle gift card per bodysuit.

Children's 3-Piece Pajama Set

Hazard: The children's pajama sets fail to meet flammability standards for children's sleepwear, posing a risk of burn injuries to children.

This recall involves children's 100 percent polyester, three-piece pajama sets that include a printed long-sleeve shirt, pants and a coordinating solid color robe that has matching printed lapels and cuffs. Each of the garments has a sewn-in side label that has "RN number 74747" printed on it, and underneath that label another sewn-in label that has PO# 3515 or 3516, a style number, and the phone number 1-800-BASS PRO. Only sleepwear in the following style numbers and with a label identifying PO# 3515 or 3516 are included in the recall: 6904536, 6904537, 6904538, 6904539, 6904540, 6904541, 6904542, and 6904543. These pajama sets were sold exclusively by Bass Pro Shops for about \$25.



Remedy: Consumers should immediately take the recalled pajama sets away from children and contact Wohali for instructions on receiving a pre-paid shipping label to return the pajama sets in exchange for a full refund in the form of a Bass Pro gift card.

One Stop Children's Pajama Sets

Hazard: The children's pajama sets fail to meet flammability standards for children's sleepwear, posing a risk of burn injuries to children.



This recall involves children's 100 percent cotton knit, two-piece, long-sleeve top and pant pajama sets. They were sold in three different styles: Santa Claus print with a white button and black and gold belt screenprint; Elf screenprint with a white Peter Pan collar, three red buttons and a black and gold belt; and reindeer

screenprint on the top with a Faire Isle pattern on the pant and a reindeer on the top. “Mad Engine” “RN 129993” and the size are on the neck label. The pajama sets were sold in children’s sizes XXS, XS, S, M, L and XL. Mad Engine claims these recalled pajama sets are counterfeit.

Remedy: Consumers should immediately take the recalled pajamas away from children and contact One Stop Shop for a full refund.



Woolino Children’s Pajamas

Hazard: The children’s pajama sets fail to meet flammability standards for children’s sleepwear, posing a risk of burn injuries to children.

This recall involves children’s 100 percent merino wool one-piece, long-sleeve, footed pajamas. They have a blue, gray, lilac or lilac gray horizontal stripe print and a zipper that extends from the center of the neckline down to the left ankle. The sleepwear was sold in sizes 6-12 months, 12-18 months, 18-24 months and 2T. Woolino and the size are printed on the back of the neckline. These pajamas were sold in stores and online for between \$50 and \$60.



Remedy: Consumers should immediately take the recalled sleepwear away from children and contact Woolino for a full refund.



Furniture



RH Metal-Wrapped Coffee Tables

Hazard: The tables' metal top can contain lead and presents a risk of lead exposure to children.

This recall involves RH Ancecy and La Salle metal-wrapped coffee tables. The recalled coffee tables are rectangular with thin sheets of dark-colored metal wrapped



around the frame to form the outside of the coffee table. Recalled coffee tables must have one of the following item numbers (61010725ZINC, 61010678ZINC, 61010728ZINC, 61190191ZINC, 61190193ZINC, or 61190195ZINC) and one of following P.O. numbers (1663995, 1819764, 1880365, 1897071, 2023453, 2060484, 2134094, 2255203, 1664594, 1819766, 1880366, 1898899, 2023457, 2079266, 2134098, 2291540, 1664595, 1819768, 1880367, 1898901, 2023459, 2079267, 2204622, 2291574, 1664598, 1826464, 1880368, 1898902, 2023463, 2079268, 2253481, 2309272, 1664599, 1826468, 1880381, 1900615, 2041955, 2079269, 2253482, 2309274, 1664600, 1826469, 1880382, 1917737, 2051946, 2079270, 2253483, 2309275, 1713610, 1826470, 1880383, 1920913, 2060479, 2079271, 2253484, 2309277, 1713611, 1859759, 1880385, 1920937, 2060481, 2079272, 2255200, 2329698, 1713612, 1859760, 1885882, 1933832, 2060482, 2079273, 2255201, 253950, 1819762, 1859761, 1885883, 1933891, 2060483, 2107239, 2255202, or 259442). Item and P.O. numbers are printed on a green sticker underneath the coffee table. If the table does not have a green sticker contact RH to determine if the table is part of the recall. These coffee tables were sold at RH Galleries and online at RestorationHardware.com for between \$1,900 and \$2,600.



Remedy: Consumers should immediately stop using the recalled coffee tables, cover the tables, and place the table out of the reach of children. Consumers can contact RH to receive a full refund or a free replacement table.

World Market Hartley Daybeds

Hazard: The removable bottom cushion on the daybed fails to meet the federal flammability standard for mattresses.

This recall involves the Hartley Flip Daybeds. The recalled daybeds are a light gray upholstered duet daybed sofa. The SKU/UPC 535790/00000025357905 is printed on the UPC label attached to the underside of the daybed. These daybeds were sold exclusively at World Market for about \$550.



Remedy: Consumers should immediately stop using the recalled daybeds and return the removable bottom cushion to any Cost Plus World Market or World Market store for a free replacement bottom cushion.



Jimco Outdoor Folding Chairs

Hazard: The chair's seat can break, posing a fall hazard.

This recall involves Jimco Outdoor Folding Bistro Chairs in graywash and teak finishes. The Bistro Chairs are wooden foldable chairs. The chairs were sold individually at TJ Maxx and Marshalls, and as part of a set with two chairs and a table at HomeGoods and Sierra Trading Post for between \$20 and \$130.

Remedy: Consumers should immediately stop using the recalled chairs and contact the firm for instructions on how to return the chairs for a full refund of the purchase price.

TJX Companies Swivel Barstools

Hazard: The wooden joints on the barstool can break, posing a fall hazard.

This recall involves TJX swivel barstools with a beige, blue or gray fabric back and seat, and wooden legs. The barstools measure about 18 inches wide, 22.8 inches deep and 40.9 inches high. One of the following tag numbers is printed on the product hang tag: 081578, 081582, 081586, 081640, 081643, 081651, 081656, 081658, 081660, 527110, 527113, 527118, 527121, 527126, 527128, 533088, 726376, 726377, 726380, 726386, 726387 and 726393. These barstools were sold at HomeGoods, Marshalls and T.J. Maxx stores nationwide for between \$100 and \$130.



Remedy: Consumers should immediately stop using the recalled barstools and return them to any Home Goods, Marshalls or T.J. Maxx store for a full refund.

Outdoor Gas Fire Pit Table

Hazard: The bowl base of the fire pits lacks a heat shield to protect consumers from burns while turning off the propane tank after use, posing a burn hazard.

This recall involves Hampton Bay 50,000 BTU, 30-inch Cross Ridge Outdoor Gas Fire Pit Table Patio Heaters with model number G-FTB51057B and UPC 6944937601579. The fire pit has an antique bronze finish with a natural slate tabletop and a black base that holds a propane tank. The model and UPC are printed on the product's packaging. These fire pits were sold by Home Depot for about \$200.



Remedy: Consumers should contact Yayi for a free repair kit which includes a heat shield and installation instructions.

West Elm Jensen Glass Tables

Hazard: The tempered glass top can shatter unexpectedly, posing a laceration and injury hazard to the user or bystanders.

This recall involves West Elm Jensen rectangular glass tables. The tables have a solid wood A-frame base and a clear glass top. The table measures 76 inches long by 36 inches wide by 30 inches high. Only rectangular tables with SKU number 4737003 or 7912629 are included in the recall. The SKU number is printed on the table's packaging. These tables were sold by West Elm for between \$480 and \$600.



Remedy: Consumers should immediately stop using the recalled tables and contact West Elm to receive a free replacement table top.

Regency Ultimate Gas Stove Fireplaces

Hazard: The pressure release system can fail and cause the gas stove to explode, posing explosion and injury hazards.

This recall involves Regency Ultimate U37 and U39 direct vent gas stove fireplaces. They were sold in black and have gold or silver trim around the glass doors. "Regency" is printed on the front, bottom left corner of the pedestals of the stoves. The following model and serial numbers are included in the recall and are printed on a label located on



the inside of the front panel door: Model U39 with ranges 41001-42602, 223000001-223008520, or 315000001-315012548 or Model U37 with ranges 13735-13763, 31001-31795, 221000025-221002269, 221031585-221031745, or 313000001-313000457.

Remedy: Consumers should immediately stop using the recalled gas stoves, turn off the gas supply to the unit, and contact Regency to schedule a free repair.

Ross Bistro Chairs

Hazard: The chair's frame can break, posing a fall hazard to consumers.

This recall involves Bronze Hammered bistro chairs. The chairs measure 37 inches tall; and have a round seat and a heart-shaped backrest. SKU number 400167187741 can be found on a tag attached to the chair or on a sticker on the underside of the seat. These chairs were sold exclusively at Ross stores nationwide for about \$25.

Remedy: Consumers should immediately stop using the recalled chairs and return them to any Ross store for a full refund.



Poppin Pitch Rolling Chairs

Hazard: The seat plate can break and detach from the seat base, posing a fall hazard.



This recall involves Pitch model rolling chairs. The chair is upholstered in fabric and was sold in five colors: Red (model #: 103772), Blue (model #: 103767), Dark Gray (model #: 103769), Khaki (model #: 103771), and Dark Blue (model #: 103768). The chair has a chrome-plated base, five roller wheels and measures about 33 inches tall and 25.5 inches wide. The Poppin logo and model number are printed on the chair's seat plate underneath the chair. These chairs were sold by Poppin for about \$400.

Remedy: Consumers should immediately stop using the recalled chairs and contact Poppin for a free repair, including a new seat plate mechanism and installation.

Hillsdale Bar Stools

Hazard: The stool seat can loosen or break off at the base, posing a fall hazard to the user.

This recall involves Polston and Collin models of swivel backless bar stools. The Polston bar stools have a tan seat cushion and metal base with four legs and were sold in a mocha color. The Collin bar stools have a wooden seat and metal base with four legs and were sold in two colors: mocha and white. The model number is printed on the packaging and in the assembly instructions. Affected model numbers include: 6316-826, 6316-830, 6327-831, and 6316-832.



Remedy: Consumers should immediately stop using the recalled bar stools and contact Hillsdale Furniture for a full refund.

Land of Nod Toddler Beds

Hazard: The headboard can disconnect from the bed frame and fall onto the bed, posing an entrapment hazard to children.

This recall involves The Land of Nod’s Nook toddler beds. The toddler bed has a green



and gray headboard with a gray footboard. “The Land of Nod”, “Made in Vietnam” and SKU number “404485” are printed on a label attached to toddler bed headboard and footboard.

Remedy: Consumer should immediately take the recalled toddler bed away from children and contact The Land of Nod for instructions on receiving a full refund.

Marseille Dining Benches

Hazard: The foam seat cushion and base can crack in the middle and cause the bench to collapse, posing a fall hazard.



The recall involves Marseille dining benches with four legs. The benches were sold in black and brown with beige linen seat cushions. The benches were made of rubber wood. The bench measures about 52 inches by 18 inches wide. The model number is VH1103 and can be found on the product label on the bottom of the bench. These benches were sold in retailers nationwide and online for about \$150.

Remedy: Consumers should immediately stop using the recalled benches and contact Vilo Home for a full refund.

Amazon Home Life Mattresses

Hazard: The mattresses fail to meet the mandatory federal flammability standard for mattresses, posing a fire hazard.

This recall involves Basic 6-inch and Basic 8-inch models Home Life mattresses sold in twin, full, queen and king sizes. Recalled mattresses are ivory with tan and gray. “Made For: Superior Importers company, 502 Jersey Avenue, New Brunswick, NJ 08901” is printed on a white tag located on the top side near the foot of the mattress. These mattresses were sold exclusively at Amazon.com for between \$50 and \$150.

Remedy: Consumers should immediately stop using the recalled mattresses and contact Superior Importers or the place of purchase for instructions on receiving a free mattress cover to bring the mattress into compliance with the federal standard.



Crate and Barrel Dakota Benches

Hazard: The benches can tip over while in use, posing a fall hazard.

This recall involves the Dakota wooden bench.

The bench has two legs and was sold in two sizes: 51 inches wide by 18 inches tall and 71 inches wide and 18 inches tall. These benches were sold by Crate and Barrel for between \$600 and \$800.

Remedy: Consumers should immediately stop using the recalled benches and contact Crate and Barrel for a free repair.



Dream On Me Crib and Toddler Bed Mattresses

Hazard: The mattresses fail to meet the mandatory federal flammability standard for mattresses, posing a fire hazard.

This recall involves Dream On Me spring and foam mattresses for cribs and toddler beds. The recalled mattresses were sold in a variety of colors and prints. The model number and date of manufacture are printed on a tag on the top center of the mattress. A complete list of recalled mattresses can be found at www.dreamonme.com and click on “Customer Care”. These mattresses were sold online for between \$40 and \$90.

Remedy: Consumers should immediately stop using the recalled mattresses and contact Dream On Me to receive a free mattress cover to bring the mattress into compliance with the federal flammability standard.



IKEA Chests and Dressers

Hazard: The recalled chests and dressers are unstable if they are not properly anchored to the wall, posing serious tip-over and entrapment hazards that can result in injuries or death to children.

This recall reannouncement involves MALM and other IKEA chests and dressers that do not comply with the requirements of the U.S. voluntary industry standard (ASTM F2057-14). The

recalled children's and adult chests and dressers include the MALM 3-drawer, 4-drawer, 5-drawer and three 6-drawer models and other non-MALM models. The recalled children's chests and dressers are taller than 23.5 inches; recalled adult chests and

dressers are taller than 29.5 inches. The MALM chests and dressers are constructed of particleboard or fiberboard and are white, birch (veneer), medium brown, black-brown, white stained oak (veneer), oak (veneer), pink, turquoise, grey, grey-turquoise, lilac, green, brown stained ash (veneer), and black. A 5-digit supplier number, 4-digit date stamp, IKEA logo, country of origin and "MALM" are printed on the underside of the top panel or inside the side panel. To see a complete list of other non-MALM chests and dressers included in this recall, click on this link [www.IKEA-USA.com or http://www.ikea.com/ms/en_US/ikea-chest-and-dresser-recall/index.html](http://www.ikea.com/ms/en_US/ikea-chest-and-dresser-recall/index.html) on IKEA's website.



Remedy: Consumers should immediately stop using any recalled chest or dresser that is not properly anchored to the wall and place it in an area that children cannot access. Contact IKEA for a choice between two options: refund or a free wall-anchoring kit. IKEA will pick up the recalled dressers free of charge or provide a one-time, free in-home wall-anchoring service for consumers upon request.

Rockler Murphy Bed Hardware Kits

Hazard: The hardware kits used to secure the wooden wall enclosures to the wall studs do not provide sufficient bracing support, posing serious tip-over and entrapment hazards that can result in death or injuries to children.



This recall involves all I-Semble vertical and horizontal Murphy Bed hardware kits. The kits are used to assemble fold down beds and were sold in three sizes: twin, full and queen. The model numbers for the I-Semble vertical-mount Murphy bed hardware kit with mattress platform are: twin size, model #54877, full size, model #55991 and queen size, model #54386. The I-Semble horizontal-mount Murphy bed hardware kit with mattress platform twin size, model #50479, full size, model #53155 and queen size, model #58262 . They include a metal bed frame with wood slats for the mattress platform, a metal leg to support the foot of the mattress platform, mounting brackets to attach the metal bed frame to the wooden enclosure built by consumers, wall brackets to secure the wood enclosure to wall studs, and associated screws and bolts. These kits were sold by Rockler for between \$300 and \$400.

Remedy: Consumers should immediately stop using Murphy beds built using the recalled hardware kits, and contact Rockler for a free replacement repair kit with instructions.

Sleep Number 360 Smart Bed Foot Warmers



Hazard: The foot warmer under the mattress cover can short circuit and overheat, posing a burn hazard.

This recall involves the foot warmer sold exclusively with Sleep Number 360 smart beds (models i7 and i10) when combined with a FlexFit 3 adjustable base. The beds were sold in the

following sizes: TwinXL, Full, Queen, King, FlexTop King, Cal King, Split King, Split Cal King and FlexTop Cal King and were also provided for consumer research purposes to select consumers beginning in November 2016.

Remedy: Consumers should immediately stop using and disable the foot warmer in their Sleep Number 360 smart bed using the instructions provided by the company.



Household Goods



Lifetone Bedside Fire Alarm and Clock

Hazard: The bedside fire alarm can fail to operate and fully alert consumers to a fire.

This recall involves Lifetone HLAC151 Bedside Fire Alarm and Clock with serial numbers ranging from AC160600001 through AC160604102 and AC170100001 through AC170106030 only. The serial number is printed on the left side of the silver sticker on the bottom of the unit. The bedside alarm and clock is an assistive alerting device intended for in-home use by individuals with hearing loss. These alarms were sold online at www.lifetonesafety.com for about \$215 and installed by fire departments and the American Red Cross nationwide from November 2016 through September 2018.



Remedy: Consumers should immediately stop using the recalled product and contact Lifetone Technology for instructions on receiving a free replacement.

Mountain Warehouse Children's Water Bottles



Hazard: The water bottle's spout can detach, exposing a small ring that poses a choking hazard to children.

This recall involves a plastic 350ml children's water bottle. The water bottles come with a screw on solid color top with a pop-up straw and handle. The water bottles were sold in multiple colors and prints including: tractors, hedgehogs, sharks, fish and horses. Only these bottles are included in the recall. These bottles were sold at Mountain Warehouse stores nationwide and online from July 2017 through September 2018 for about \$10.

Remedy: Consumers should immediately stop using the bottles, take them away from children and contact Mountain Warehouse for a full refund.

Numbify, Pre-TAT Tattoo, Superior Pain & Itch Relief, and Soothing Sore Relief

Hazard: The packaging is not child resistant as required by the Poison Prevention Packaging Act. These creams, sprays and gels contain lidocaine, posing a risk of poisoning to young children if they put it on their skin or ingest it.



This recall involves all Pain Relief Naturally lidocaine-containing products including Numbify, Extra Strength Numbify, Pre-TAT Tattoo, Superior Pain & Itch Relief, and Soothing Sore Relief creams, sprays, gels and liquid gels. The recalled products were sold in 1, 2 and 4 ounce size containers. The products have black packaging with the name of the product in gold, red, or green lettering.

Remedy: Consumers should immediately store the product in a safe location, out of reach of children and contact the firm to receive a free replacement cap.

Brookstone Wireless Speakers

Hazard: The lithium ion batteries in the wireless speakers can overheat and catch fire, posing a fire hazard.

This recall involves Brookstone Big Blue Party indoor/outdoor wireless speakers. The recalled speakers are silver or gray colored and measure about 6 inches wide by 6 inches deep by 16 inches tall. Recalled SKU numbers include: 849504, 318417, and 952645. The SKU is printed on the bottom underside of the speaker. These speakers were sold at retailers nationwide and online for about \$200.



Remedy: Consumers should immediately stop using the recalled speakers and properly dispose of the lithium-ion battery packs according to state and local regulations. Brookstone has filed for Chapter 11 bankruptcy protection. Contact 866-576-7337 toll-free or visit the Omni Management Group website for information about a possible refund.

Wireless Charger Bedside Pockets

Hazard: The charging pockets can overheat, posing fire and burn hazards.

This recall involves Kikkerland's wireless charger bedside pockets used for recharging mobile phones and devices. The recalled charger pockets have the configuration of an expanding v-shaped file folder with a single pocket and a rigid flap that is pivotally attached on one side. The pocket is typically placed between the mattress and the bed frame. They are made of a dark gray felt material and were sold with a power cord. In operation, the cord is plugged into an electronic outlet and the mobile phone is placed into the pocket for recharging. These pockets were sold at retailers nationwide and online for about \$35.



Remedy: Consumers should immediately stop using the recalled charger pockets and contact Kikkerland for instructions on how to receive a full refund.

Cracker Barrel Decorative Driftwood Pineapples

Hazard: The metal leaves on top have sharp edges, posing a laceration hazard.




This recall involves decorative driftwood pineapples. They are shaped from tan driftwood spikes, have spiked, galvanized metal leaves at the top and measure approximately 19 inches high by 9.5 inches wide by 9.5 inches in diameter. These pineapples were sold exclusively at Cracker Barrel Stores for about \$40.

Remedy: Consumers should immediately stop using the recalled pineapples and return them to any Cracker Barrel Old Country Store for a full refund.

Uber Numb Topical Cream and Spray

Hazard: The packaging is not child resistant as required by the Poison Prevention Packaging Act. The pain-relieving cream and spray contain lidocaine, posing a risk of poisoning to young children if they put it on their skin or ingest it.



This recall involves UberScientific Uber Numb Topical Anesthetic Cream and Uber Numb Spray. The recalled cream is in a white jar with a smooth, rounded cap and a green label with “Uber Numb Topical Anesthetic Cream” printed on the front. The cream was sold in one, two and four ounce sizes with the lot numbers printed on the bottom of the jar and the UPC number printed on the label to the left of the product name. Recalled lot numbers for the cream include A23Z3, F12Z5, L06Z2A, L06Z2B, B01N2A, E10Z4, L06Z2, and B01N2. The recalled spray is in a green bottle with a white cap and has a white label with “Uber Numb Spray” printed on the front. The spray was sold in four ounce size with the lot numbers printed on the bottom of the bottle and the UPC number printed on the label to the right of the product name. Recalled lot numbers for the spray include K30Z6 and B09N2. These products were sold online for between \$20 and \$40.

Remedy: Consumers should immediately place out of reach of children and contact UberScientific for instructions on how to receive a free replacement or full refund.

IKEA CALYPSO Ceiling Lamps

Hazard: The glass shade on the ceiling lamp can detach and fall, posing impact and laceration hazards to consumers.

This recall involves IKEA CALYPSO ceiling lamp units with manufacturing date codes between 1625 and 1744. The manufacturing date code is printed on a sticker on the light bulb socket base plate. Use caution when removing the lamp shade to see the sticker and code. These lamps were sold at IKEA stores nationwide and online for about \$30.



Remedy: Consumers should immediately stop using the recalled ceiling lamps and return them to any IKEA store for a full refund or replacement lamp.

Desert Harvest Relèveum Skin Repair Cream

Hazard: The bottles are not child resistant as required by the Poison Prevention Packaging Act.

The recalled Desert Harvest Relèveum Skin Repair Cream is in a transparent green bottle with a white pump dispenser cap and a tan/white gradient label with “Desert Harvest Relèveum” printed on the front. The product is an over the counter skin cream with lidocaine (4%) as the active ingredient. The cream is sold in a 4-ounce or an 8-ounce bottle with the date code “D02N5” printed above the barcode on the bottle. These creams were sold at pharmacies nationwide and online for between \$27 and \$50.



Remedy: Consumers should immediately place the recalled pain-relieving cream out of the reach of children and contact Desert Harvest for a free replacement child resistant cap for the bottle.

Rust-Oleum Black Satin Countertop Coating

Hazard: The counter coating contains lead levels that exceed the federal lead paint ban.



This recall involves one-quart containers of Rust-Oleum black satin countertop coating with product number 263209 and batch code P7612D. The product number and batch code are printed on the bottom of the can. This coating was sold at retailers nationwide and online for about \$20.

Remedy: Consumers should immediately stop using the recalled countertop coating and contact Rust-Oleum. Consumers who have not used the countertop coating will receive a full refund plus \$25 to return the product to Rust-Oleum. Consumers who have applied the recalled countertop coating will receive a repair kit or replacement of the affected surfaces.

PetSmart Reptile Strip Light Fixtures

Hazard: The strip light's fluorescent bulb can overheat causing the hood on the light fixture to ignite, posing a fire hazard.



This recall involves 20-inch and 30 inch All Living Things reptile strip light fixtures. These light fixtures simulate natural daylight and are attached to the top of the reptile's terrarium. The 20-inch fixture has UPC number 73725773305 and the 30-inch fixture has UPC number 73725773306 printed on the packaging. These lights were sold at PetSmart stores nationwide about \$35 to \$40.

Remedy: Consumers should immediately stop using the recalled light fixtures and return them to any PetSmart store for a full refund.

Vornado Electric Space Heaters

Hazard: The electric space heater can overheat when used, posing fire and burn hazards.

This recall involves Vornado VH101 Personal Vortex electric space heaters sold in the following colors: black, coral orange, grayed jade, cinnamon, fig, ice white and red. The heaters measure about 7.2 inches long by 7.8 inches wide by 7.10 inches high and have two heat settings (low and high) and a fan only/no heat setting. "Vornado" with a "V" behind it is printed on the front of the unit. The model/type "VH101," serial number and ETL mark are printed on a silver rating label on the bottom of the unit. These heaters were sold at retailers nationwide and online for about \$30.



Remedy: Consumers should immediately stop using the recalled heaters and contact Vornado for instructions on how to receive a full refund or a free replacement unit.

Xtava Allure Hair Dryers

Hazard: The hair dryer and power cord can overheat and catch on fire, posing fire, burn and shock hazards.

This recall involves the Allure and Allure Pro 2200W ionic ceramic hair dryers. The hand-held hair dryers are black or white and include a concentrator nozzle. The hair dryers were sold separately or as part of various hair care kits. Many of the units have a label located underneath the back of the unit bearing the following SKU numbers: XTV010001, XTV010001N, XTV010002, or XTV010002N. All units have “xtava” imprinted on the blower end of the hair dryer. These hair dryers were sold online for between \$15 and \$80.



Remedy: Consumers should immediately stop using the hair dryers and contact Xtava to receive a free replacement hair dryer.

Koehler-Bright Star Flashlights



Hazard: The flashlights are missing an encapsulation on a circuit board component which protects the flashlight from igniting, posing an injury hazard to the user or bystander.

This recall involves WorkSafe 3-D cell flashlights, model number 2224 LED. The model number is printed at the top right side of the text contained on the flashlight. The flashlight is safety orange with a black reflector assembly and black end cap and measures about 10.25 inches long by 2 inches in diameter. Only 3-D cell flashlights that do not contain a date code stamped on the body of the units are included in the recall. These flashlights were sold in retailers and online for about \$21.

Remedy: Consumers should immediately stop using these recalled flashlights and inspect the flashlights for a missing date code on the body of the flashlights. If the recalled flashlight does not have a date code, contact Koehler-Bright Star for free replacement parts.

Harbor Freight Handgun Safe

Hazard: The handgun safes can open without the use of a key or combination upon impact and allow unintended access to the contents of the safe, posing a risk of serious injury to children and others.



This recall involves two models of 0.17 cubic foot capacity electronic handgun safes sold under two different brand names,

Union Safe Company and Bunker Hill Security. The recalled safes are dark gray and the SKU number is printed on a permanent label on the door. The brand is printed on the permanent label on the door and molded into the combination touch-pad panel. Affected SKU include 62984 and 61581. These safes were sold exclusively at Harbor Freight and online at HarborFreight.com for about \$65.

Remedy: Consumers should immediately stop using the recalled handgun safes, secure the handguns to keep them away from children and return the safes to any Harbor Freight Tools location for a full refund of the purchase price in the form of a Harbor Freight Tools gift card.

Zebra Printer Power Supply Units

Hazard: The power supply units can degrade and corrode over time when exposed to moisture and overheat, posing a fire hazard.

This recall involves power supply units that serve as the power source for models of Zebra manufactured thermal industrial printers (sold under the Zebra brand, including co-branded or re-branded) used to make bar codes and other commercial labels. The Zebra logo or FSP North America logo, date code and part number are printed on the power supply unit. The power supply units were sold as after-market kits or included with the sale of the following models of printers manufactured by Zebra:



Printer Model	Power Supply Unit		Date Codes			
	PART NUMBER	WATTAGE				
APCES-1	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX			
APCS-1						
APES-1						
APS-1						
BR100i	808099-002	70-Watt Brick	0639XX through 1253XX			
BR110i						
BR120i						
CN100i	808099-002	70-Watt Brick	0639XX through 1253XX			
CN110i						
CN120i						
GC420d	808113-001 or P1028888-001	60-Watt Brick	0639XX through 1253XX			
GC420t						
GK420d	808099-001 or P1028888-006	70-Watt Brick	0639XX through 1253XX			
GK420t						
GK888-DT	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX			
GK888-TT						
888-DT						
888-TT						
GX420d	808101-001	100-Watt Brick	0639XX through 1253XX			
GX420t						
GX42S						
GX430d	808101-001	100-Watt Brick	0639XX through 1253XX			
GX430t						
GT800	808099-001 or P1028888-003	60 or 70-Watt Brick	0639XX through 1253XX			
GT810						
GT820						
GT830						
HC100	808099-003	70-Watt Brick	0639XX through 1253XX			
H 2824-Z	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX			
H 2844-Z						
J100i	808099-002	70-Watt Brick	0639XX through 1253XX			
J110i						
J110m						
J120i						
LP 2824	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX			
LP 2824-Z						
LP 2824 Plus						
LP 2824 Plus CVS	808113-002 or P1028888-007	50 or 60-Watt Brick	0639XX through 1253XX			
LP 2844	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX			
LP 2844-AP						
LP 2844 e						
LP-2844 L						
LP-2844 Le						
LP-2844-P						
LP 2844ps						
LP 2844-Z						
LP 3842				808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX

Printer Model	Power Supply Unit		Date Codes
	PART NUMBER	WATTAGE	
LP 3842 SP	P1035373	100-Watt Brick	0639XX through 1253XX
LP 3844-Z	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX
LP384Z			
P100i	808099-002	70-Watt Brick	0639XX through 1253XX
P110i			
P110m			
P120i			
PS4000	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX
R2844	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX
2844-R			
R2844-Z			
R402	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX
T208M	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX
T212M			
Thermal 2844	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX
Thermal 2844 ATP			
2844 ATP			
Thermal 2844 e			
Thermal 2844 L			
Thermal 2844 Le			
TLP 2824	808113-001 or P1028888-001	50 or 60-Watt Brick	0639XX through 1253XX
TLP 2824-Z			
TLP 2824 Plus			
TLP 2844			
TLP 2844-P			
TLP 2844-Z			
TLP 3824			
TLP 3842			
TLP 3844-Z			
WM120i	808099-002	70-Watt Brick	0639XX through 1253XX
SC120i			
ZP450	808102-001 or P1028888-002	60-Watt Brick	0639XX through 1253XX
ZP450 ctp			
ZP455	808099-001 or P1028888-006	70-Watt Brick	0639XX through 1253XX
ZP455 atp			
ZP455 ctp			
ZP455	808101-001	100-Watt Brick	0639XX through 1253XX
ZP500	808102-001 or P1028888-002	60-Watt Brick	0639XX through 1253XX
ZP500 EPL			
ZP500 ZPL			
ZP500 Plus			
ZP500 Plus EPL			
ZP500 Plus ZPL			
ZP505			
ZP505 EPL			
ZP550	808102-001, 808102-002, or P1028888-002	60-Watt Brick	0639XX through 1253XX
ZXP Series 1, 3 and 3C	808101-001	100-Watt Brick	0639XX through 1253XX

These printers and power supplies were sold from 2006 through 2013 with printers priced from \$340 to \$2,000.

Remedy: Printer owners should immediately stop using the recalled power supply units and contact Zebra for a free replacement power supply.



Vitamix Ascent and Venturist Blending Containers

Hazard: The containers can separate from the blade's base exposing the blades, posing a laceration hazard to consumers.

This recall involves Ascent™ and Venturist™ series 8-ounce and 20-ounce blending containers with blade date codes March 2018 (“03-18”) or earlier. Date codes are in the format MM-YY; for example, March 2018 is “03-18.” If the blade base is marked on the bottom with a green or orange dot, the container has already been repaired. The Vitamix logo is printed on the blending container. The blade date code is laser-etched onto the top of the blade in the blade base. The products have a clear container and a black blade base and were sold separately and with Vitamix Venturist™ Model 1200 blenders. These containers were sold in stores nationwide and online for between \$24 and \$500 for the blender and blending container set.



Remedy: Consumers should immediately stop using the recalled blending containers and contact Vitamix for a free repair kit.

Stanly LED Light and Power Stations

Hazard: The recalled workbench and power stations are wired incorrectly, posing shock and electrocution hazards.



This recall involves Stanley LED workbench light and power stations with model number WLB40PS. The recalled units were sold in black/yellow color and measure about 19.75 inches long by 3.75 inches wide and 5 inches tall. They have a 40-chip LED shop light with adjustable angles, four power outlets and an on/off switch mounted on the unit. “Stanley” is printed in yellow by the outlets. The model number is printed on a sticker located on the back of the lighting panel. These lights were sold in stores nationwide and online for between \$25 and \$40.

Remedy: Consumers should immediately stop using the recalled workbench and power stations, unplug the cord and contact Baccus Global for a free replacement or full refund.

Amnon Floor Lamps



Hazard: The incorrect label on the lamp states that consumers can use 40 watt lightbulbs. However, the socket is only designed to support 25 watt lightbulbs. Use of incorrect wattage lightbulbs can melt the power switch, posing a burn hazard.

This recall involves Signature Design by Ashley Amnon floor lamps with a floor switch and 12 lightbulb sockets. The portable, electric floor lamps are metal with a bronze finish and measure about 64 inches tall. Model number L207971 is printed on a label on the underside of the lamp’s base. These lamps were sold in stores and online for between \$160 and \$300.

Remedy: Consumers should immediately stop using and unplug the recalled floor lamps and contact Ashley Furniture for instructions on how to receive a full refund of the purchase price.

“Ball Bullet” Fireworks

Hazard: The recalled fireworks are overloaded with pyrotechnics intended to produce an audible effect, violating the federal regulatory requirements for this product. Overloaded fireworks can result in a greater than expected explosion, posing burn and explosion hazards to consumers.



This recall involves ball bullet fireworks packed in bags of four with model number LB6103 and M-150 cracker fireworks packed in boxes of 36 with model number LA150B. The model numbers are printed on the packaging. The recalled fireworks were sold with four different colored fireworks and have “Ball Bullet Rocket” printed on the packaging. The M-150 cracker fireworks were sold in a yellow/orange box and have “Legend Fireworks M-150 Cracker 36 Pieces” printed on the front of the box. These fireworks were sold for between \$4 and \$13.

Remedy: Consumers should immediately stop using the recalled fireworks and return them to the place of purchase for a full refund.

Uttermost Hanging Décor

Hazard: The hanging hardware can break and allow the décor to fall, posing an injury hazard to bystanders.

This recall involves various types of mirrors, art and wall décor sold with adjustable j-hook hanging hardware. The recalled hardware has item number 1703, 1704, 1705 or 1706 printed on the back bottom portion of the j-hook and on the hardware’s box. The recalled adjustable j-hooks measure approximately 3.5 inches long and 0.75 inches wide.



Remedy: Consumers should immediately take the recalled décor off the wall and inspect the hanging hardware to check for the recalled metal adjustable j-hooks. If the décor has the recalled metal adjustable j-hooks, do not re-hang the recalled décor. Consumers with recalled metal adjustable j-hooks should contact Uttermost to receive free replacement adjustable j-hooks with free shipping.

CloudCharge Qi Wireless Charging Pads

Hazard: The wireless chargers can overheat while in use, posing a burn hazard.

This recall involves the CloudCharge Qi Wireless Charging Pad. The charging pads were a promotional giveaway. The product name and model number T4706 are printed on the bottom of the product. The recalled chargers are circular and have a white plastic bottom with the top having various promotional artwork. They measure about 4” in diameter and .5” tall. A white USB power cable is included along with a wireless receiver adapter. Each charging pad and accessories are packed in a white plastic box with a clear lid. This recall involves only one production lot (Version 2) of the charging pad.



Remedy: Consumers should immediately stop using the recalled chargers and contact Hirsch Gift for a free replacement.

Sandoz and Novartis Prescription Drug Blister Packages

Hazard: The prescription drug packaging is not child resistant as required by the Poison Prevention Packaging Act, posing a poisoning risk if swallowed by children.



This recall involves blister packages of prescription drugs from Novartis and Sandoz. The drugs are packaged with 3 to 10 tablets per blister card. The recalled Novartis prescription blister packages have “Novartis,” the name of the drug, dosage, NDC, lot number and expiration date printed on the cartons and the blister cards. The recall includes the following: Zofran ODT and Entresto packages. The recalled Sandoz prescription blister packages have “Sandoz,” the name of the drug, dosage, NDC and lot number printed on the cartons and the blister

cards. The recall includes packages for the following: Azithromycin, Donepezil ODT, Haloperidol, Imipramine HCl, Isosorbide Dinitrate (ISDN), Naratriptan, Ondansetron, Ondansetron ODT, Perphenazine, and Risperidone ODT.

Remedy: Consumers should immediately secure the blister cards to keep them out of the sight and reach of children and contact Novartis or Sandoz for further instructions. Novartis and Sandoz advise that consumers should continue to use the medication as directed once the blister packages are secured out of reach of children.

Loxex Video Monitors

Hazard: The video monitor's batteries can overheat, swell and expand and cause the battery cover to open or come off and expose hot batteries, posing a burn hazard to consumers.

This recall involves Loxex brand video monitors models LW2751, LW2752 and LW2962H used with surveillance video systems. The video monitors are black and were sold in two sizes, 7-inch-wide and 9-inch-wide. The video monitors contain a blue lithium polymer battery. The model and serial numbers are printed on the top or on the back panel of the monitors. Only monitors with the following model and serial numbers are included in the recall: Model LW2751 with serial number ranges WA01140315501-WA01140319000, WA02140417501-WA02140419000, WA0314050251-WA0314051250, WA0314060001-WA0314061500, WA03140627347-WA03140629346, WA03141222601-WA03141223169 and WA04141223170-WA04141223350; model LW2752 with serial number ranges WA01140422265-WA01140423264, WA0214065501-WA0214066500, WA02140629347-WA02140630346, and WA03141121501-WA03141122000; and model LW2962H with serial number ranges WA01140329001-WA01140332400, WA02140419001-WA021404220500, WA02140422001-WA02140422100, WA0314051251-WA0314053250, WA0314061501-WA0314061618, WA0414061619-WA0414063000, WA04140623347-WA04140625346, WA0514112501-WA0514114000, and WA05141122501-WA05141125000.



Remedy: Consumers should immediately stop using the recalled monitors and contact Loxex for instructions on receiving a full refund.



Crate and Barrel Josephine Floor Mirrors

Hazard: The mirror's glass can separate from the wooden backing and fall, posing a laceration hazard.

This recall involves Crate and Barrel's Josephine floor mirrors, sold individually or as a set of three mirrors that can be hung vertically or horizontally. The mirror consists of a larger rectangular mirror and a smaller square mirror on wooden backing that measures about 16 inches

wide, 3 inches deep and 90.5 inches long. The hangtag that came with the mirror has the number 215-037 printed next to the bar code. These mirrors were sold exclusively at Crate and Barrel stores and online at CrateandBarrel.com for between \$450 and \$1,250 for the set of three.

Remedy: Consumer should immediately stop using the recalled mirrors and contact Crate and Barrel to arrange for a free replacement mirror.

GE Cool White T8/T12 LED Tube Lamps

Hazard: The pins on one end of the lamp can be energized during installation/removal, posing electric shock and electrocution hazards.

This recall involves GE Lighting's 31243 LED13T8U840 LED two pack tube lamps. These units are most often used in garages, basements, workshops and utility rooms. The GE logo and model information are printed on a label near the tube's base. These lamps were sold exclusively at Lowe's and online at Lowe.com for about \$15.

Remedy: Consumers should immediately contact GE Lighting to receive instructions on safely removing the LED tube lamps, and to receive a refund in the form of a \$17 Lowe's store credit. Consumers should make sure the light switch is "off" before attempting to change LED tube lamps.



Bluefin Wireless Chargers

Hazard: The wireless phone charger can overheat while in use, posing a burn hazard to consumers.

This recall involves wireless smart phone chargers with model number AC16B printed on the bottom. The recalled chargers are circular and have clear edges and a white plastic center with black trim. They measure about 3.9" in diameter and 0.4" tall. A black USB cable is included with the chargers.



Remedy: Consumers should immediately stop using the recalled chargers and contact Bluefin for a full refund.



Michaels 3-Tier Candle Holder

Hazard: The candle holder can ignite, posing fire and burn hazards.

This recall involves Michaels private brand Ashland 3-tier haunted townhouse candle holders. The candle holders were sold in black, measure about 20 inches tall by 7 inches wide by 5 inches deep and have two columns of three vertically stacked candle holders. Only 3-tier haunted townhouse candle holders with SKU number 513180 and UPC code 886946019340 printed on a hangtag are included in the recall. These candle holders were exclusively sold at Michaels stores and online at Michaels.com for about \$30.

Remedy: Consumer should immediately stop using the recalled candle holders and return them to any Michaels store for a full refund.

Kohler Automatic Generator Transfer Switches

Hazard: The transfer switch can fail and overheat, posing a fire hazard.

This recall involves Kohler 100-amp service entrance rated automatic transfer switches used with Kohler brand residential and commercial generators. “Kohler” is printed on the outside panel. Model number RXT-JFNC 100ASE and the serial number are printed on a nameplate located on the inside cover of the unit. These switches were sold for about \$530.



Remedy: Consumers should immediately contact an authorized Kohler service representative or Kohler directly to schedule a free repair.

Ambiano Mini Deep Fryers

Hazard: The deep fryer heating element can overheat, posing fire and burn hazards.

This recall involves Ambiano mini deep fryers sold in two colors, brushed stainless steel and red. The recalled deep fryers have a black lid and were sold with a metal food basket. The deep fryers measure about 9.45 inches wide by 10.43 inches high by 8.23 inches



deep. The units have Ambiano printed on the front. The barcode numbers listed below can be found on the bottom of the unit on the silver rating label. The following barcode numbers are included in the recall: 20072483 and 20072490. These fryers were sold at ALDI stores nationwide for about \$15.

Remedy: Consumers should immediately stop using the recalled deep fryers and return it to their local ALDI store for a full refund.

Sharper Image and Frigidaire Mandoline Slicers

Hazard: The small blades in the julienne slicer attachment can separate from the plastic assembly, posing a laceration hazard.



This recall involves The Sharper Image and Frigidaire Mandoline slicers. The recalled slicers are a non-electric food preparation item used to slice vegetables. The slicers have a clear plastic container to capture the sliced food, two blade attachments (one large-blade slicer and one small-blade julienne slicer), a holder for the attachments and a plastic knob component to move and hold the food. The model number and UPC code are printed on the packaging. “Frigidaire” is printed on the side of the Frigidaire slicers. Affected UPC codes include 709996669580 and 709996709118. These slicers were sold at retailers and online for between \$13 and \$20.

Remedy: Consumers should stop using the recalled slicers and contact Premier Kitchen Products for instructions on how to receive a refund in the form of a \$15 gift card.

Seasons Ceiling Fans

Hazard: The brackets connected to the fan blades can break and allow the blades to fall, posing an impact hazard.

This recall involves Seasons-branded 52” five-blade ceiling fans. The recalled fans were sold in white, brass, bronze, and brushed nickel finishes and have zero, one, three or four lights. Model numbers 269702, 269712, 269714, 269716, 269718, 269808, 269810, 269812, 269816, 269818, 269820 and 269822 are included in this recall. The model



number is printed on a label on top of the motor housing.

Remedy: Consumers should immediately stop using the recalled fans and contact HD Supply to receive a free repair kit.

Hydro Pro Water Bottles

Hazard: The pink paint on the outside of the bear water bottle contains levels of lead that exceed the federal lead paint standard.

This recall involves Base Brands children's Reduce Hydro Pro Furry Friends water bottles. The stainless steel insulated, 14-ounce water bottles were sold in a pack of two bottles: a pink bottle with a character of a bear face and a gray bottle with the character of a lamb head. The recalled water bottles have a removable lid gasket and a rubber carry strap. These bottles were sold at Costco stores nationwide and online for about \$13.



Remedy: Consumers should immediately stop using the recalled water bottles, take them away from children and return them to any Costco store for a full refund. Consumers who purchased a water bottle via Amazon should contact Base Brands for a free replacement water bottle, including shipping, or a full refund.

Primark Decorative Pillows and Cushions



Hazard: The cushions can catch fire if exposed to an ignition source, posing a fire hazard.

This recall involves 21 different Primark decorative cushions. The cushions were sold in various colors and shapes, including square, rectangular, heart-shaped, unicorn-shaped, and pumpkin-shaped. The product code is printed on the label attached to the cushion. The following product codes are included in

the recall: 0608803, 0608804, 0608805, 0608806, 0608808, 0822101, 0822102, 4467001, 4467002, 4727601, 5512101, 5512102, 5512103, 8191201, 8191202, 9752806, 3685901, 4467701, 5912001, 4467201, and 8167401. These cushions were sold at Primark stores for between \$5 and \$9.

Remedy: Consumers should immediately stop using the cushions and return the cushions to a Primark store for a full refund.



Jo-Ann Holiday Light Sets

Hazard: The light set's glass jars can break during normal use, posing a laceration hazard.

This recall involves Jo-Ann's battery-operated Maker's Holiday 10-count LED string light sets. The light sets consist of ten glass jars with white plastic snow and red plastic beads inside and a cork at the top that holds the LED bulb. The light strings measure about 73.5 inches long and have a tag attached with instructions as to how to replace the batteries. Maker's Holiday is printed on the front of the product packaging and SKU/UPC

1554-7201/603559321277 on the bottom left of the back side of the product packaging. These light sets were sold at Jo-Ann stores nationwide for about \$14.



Remedy: Consumers should immediately stop using the light sets and contact Jo-Ann stores for a full refund.

Re-Fuel Power Bank Charging Stations

Hazard: When the unit is being charged, it can overheat, posing fire and burn hazards.

This recall involves the Re-fuel by Digipower Grab and Go Family Pack portable power bank charging stations. The power bank charger is a self-contained energy source used to charge cell phones and other devices when an electrical outlet is not available. The unit consists of three (black, gray and green) 2600 mAh re-chargeable lithium-ion battery chargers that sit on a recharging docking station. “re-fuel by DIGIPOWER” is printed on each power bank. Item number RF-TRIP is printed on the bottom of the charging station. These chargers were sold by The Container Store for about \$40.



Remedy: Consumers should immediately stop using the recalled charging stations and contact The Container Store for instructions on how to receive a full refund.

Scotch Laminators

Hazard: The plastic enclosure can overheat, posing a burn hazard.

This recall involves Scotch thermal laminators that are white with teal accents. They are used to laminate documents such as artwork and photos. The laminators have “Scotch” printed on the front. They measure 14 inches by 3.8 inches by 2.75 inches. The model number TL901C is printed on a sticker on the bottom of the laminator. Only laminators



with model number TL901C and teal accents are included in the recall.

Remedy: Consumers should immediately stop using the recalled laminators and contact 3M for a full refund.

H-E-B GTC Halogen Bulbs

Hazard: The halogen light bulbs can shatter while in use in a lamp or light fixture, posing laceration and fire hazards to consumers.

This recall involves GTC halogen light bulbs. They were sold in packages of 2 or 4 bulbs. The bulb packages were sold in 25 watt, 40 watt, 60 watt, 75 watt, or 100 watt bulb varieties in either

clear or soft white colors. The bulbs measure approximately 4.5 inches in length and 2.375 inches in diameter. The tops of the bulbs read “GTC” and include the wattage and lumens values. The UPC codes are printed on the product packaging. Only bulbs with the following UPC codes are included in the recall: 4122043932, 4122065268, 4122017409, 4122017463, 4122017576, 4122065608, 4122084562, 4122029652, 4122029783, 4122065177, 4122030062, 4122017464, 4122017397, 4122065271, and 4122017418.



Remedy: Consumers should immediately stop using the recalled halogen light bulbs and return them to H-E-B for a full refund.

LC Electric Blankets

Hazard: The blankets’ heating coils can overheat, posing fire and burn hazards.

The recall involves Shop LC’s heated micro plush flannel sherpa throw blankets. The blankets were sold in gray, blue, beige, red or brown and measures about 50 by 60 inches. All blankets with date code 22217 and model number OB205B2 are included in the recall. The date code is printed on the bottom right corner of the textile label, sewn on the fleece side of each blanket.



Remedy: Consumers should immediately stop using the recalled blankets and contact Shop LC for a full refund.

Kidd Dual-Sensor Smoke Alarms

Hazard: A yellow cap left on during the manufacturing process can cover one of the two smoke sensors and compromise the smoke alarm’s ability to detect smoke, posing a risk of consumers not being alerted to a fire in their home.



This recall involves models PI2010 and PI9010 of Kidde dual sensor (photoelectric and ionization) smoke alarms. “KIDDE” is printed on the front center of the smoke alarm. The model number and date code are printed on the back of the alarm.

Remedy: Consumers should remove the alarm from the wall/ceiling and visually inspect it through the opening on the side of the alarm for the presence of a yellow cap. Consumers should not attempt to take apart the alarm, open the casing, or otherwise remove the yellow cap themselves. If a yellow cap is present, the consumer should immediately contact Kidde to receive instructions and request a free replacement smoke alarm. They should remove and discard the recalled smoke alarm only after they receive and install the replacement alarm. If no yellow cap is present, consumers should reinstall the smoke alarm and no further action is needed.

Envi High-Efficiency Heaters



Hazard: Improper wire crimping by the manufacturer can cause the unit to overheat, smoke, or melt, posing a burn hazard.

This recall involves Envi Wall Heaters. The heaters were sold in white and black and measure about 19 inches by 22 inches by 2 inches. The model numbers are located on the back of the unit, on the bottom left corner. The affected products have the following model numbers: HH1012T, HW1012T, HW1012N, HW1022T, HW1022N, and HH1012T-BK.

Remedy: Consumers with recalled wall heaters should immediately contact eheat for a free repair.

Combination Battery Chargers/Hand Warmers

Hazard: The chargers can overheat, posing a fire and burn hazard.

This recall involves Human Creations EnergyFlux and EnergyFlux Slim model battery chargers and hand warmers. They are used to recharge cell phones, tablets and other electronic devices with a USB port. They were sold in eight colors: black, gray, pink, red, orange, green, blue and white. “Human Creations EnergyFlux 4400 mAh” or “Human Creations EnergyFlux Slim 4400 mAh” are printed on the side of the chargers/handwarmers. EnergyFlux 4400mAh measures about 3.5 by 2.3 by 0.97 inches and EnergyFlux Slim 4400mAh measures about 4.2 by 1.7 by 1 inches. These chargers were sold exclusively on Amazon.com for about \$30.



Remedy: Consumers should immediately stop using the recalled combination battery charger and hand warmer and contact Beanworthy for a free replacement product.

AmazonBasics Power Banks

Hazard: The power bank’s battery can overheat and ignite, posing fire and burn hazards.

This recall involves six versions of AmazonBasics’ portable lithium-ion battery chargers/power banks: 16,100 mAh; 10,000 mAh; 5,600 mAh; 2,000 mAh with micro USB cable; 3,000 mAh and 3,000 mAh with USB micro cable. The rubberized or metallic power banks are black and rectangular. The power banks were sold with or without a USB charger cable and a carrying pouch. The AmazonBasics logo is printed on the front of the unit. Product ID number B00LRK8EVO, B00LRK8HJ8, B00LRK8I7O, B00LRK8IV0, B00LRK8JDC or B00ZQ4JQAA is printed on the back of the unit.



Remedy: Consumers should immediately unplug and stop using the recalled power banks and contact Amazon for instructions on how to return it for receive a full refund.

Maximum Strength Bacitracin Plus Ointment

Hazard: The packaging is not child resistant as required by the Poison Prevention Packaging Act. The pain-relieving ointment contains lidocaine, posing a risk of poisoning to young children.

This recall involves Maximum Strength Bacitracin Plus Ointment with Lidocaine. The recalled ointment is in a white, one-ounce tube with “Bacitracin Plus” printed on the front in green. The lot number is printed on the end of the tube. The following lot numbers are included in the recall: 16001 through 16002, 404001 through 404002, 405001 through 405003, 406001 through 406004, 407001 through 407002, 415001 through 415010, 416001 through 416003, and 417001 through 417004. These ointments were sold at retailers nationwide for about \$9.



Remedy: Consumers should immediately place the recalled ointment out of the reach of children and contact United Exchange for instructions on how to receive a full refund.

Gem 8-in-1 Multicooker

Hazard: A manufacturer defect can cause the multicooker to overheat and melt on the underside, posing a fire hazard.

This recall involves Gem 65 8-in-1 model multicookers, a multifunctional, programmable cooking appliance, which includes the functions of roasting, baking, stewing, slow cooking, rice cooking, searing/sautéing, steaming and food warming. Instant Pot is printed on the front of the multicookers. Gem 65 8-in-1 and a batchcode of 1728, 1730, 1731, 1734 or 1746 are printed on the rating label on the underside of the product.



Remedy: Consumers should immediately stop using the recalled multicookers, unplug the unit and return it to Walmart to receive a full refund or contact Double Insight to receive a free replacement.

Bleeding Drip Taper Candles

Hazard: The candles' high flame can ignite the surface of the wax, posing a fire hazard.

This recall involves Cost Plus World Market's bleeding drip taper candles sold for about \$7 in a pack of two candles. The unscented wax candles are black and bleed red wax as they melt. They measure about 10 inches long. World Market, Bleeding Drip Taper Candles and SKU/UPC 544668/000000544668 can be found on the product packaging.



Remedy: Consumers should immediately stop using the recalled candles and return them to any Cost Plus World Market or World Market store for a full refund.

Rural King Electric Heated Blankets and Throws

Hazard: The blankets' and throws' electric cord can overheat and catch on fire, posing fire and burn hazards.

This recall involves Rural King's electric heated blankets and throws. The 100% polyester blankets and throws were sold in cream and brown colors and in two sizes: 50 x 60 inches (smaller than a twin size) and 84 x 90 inches (queen size). They have one or two multi-setting controllers attached to the electric cord. Model numbers starting with

BLV-OB and ending in 200, 201A, 201B, 201C, 202, 202BN, 202CM, 203, 204A1, 204A2, 204A3, 204A2BR, 204A2CM, 205B1, 205B2, 205B3 or 206C1 can be found on a corner tag. Matton Rural King Supply, Inc. is printed on the back of the tag. These blankets were sold nationwide and online for between \$30 and \$60.



Remedy: Customers should immediately stop using the recalled blankets and throws and contact Rural King for a full refund.

KitchenAid Electric Kettles

Hazard: The handle can loosen and separate from the kettle, causing hot contents to spill, posing a burn hazard.

This recall involves KitchenAid 1.7 Liter Electric Kettles. The kettles were sold in stainless steel, red, black, white, liquid graphite and cocoa silver. Model numbers and serial numbers are located on the bottom of the kettle. KitchenAid is written on the front of the kettles. A complete list of model and serial numbers included in this recall is posted on the firm's website at <http://repair.whirlpool.com>.



Remedy: Consumers should immediately stop using the recalled kettles and contact Whirlpool for a free replacement.

ISO Ionic Hair Dryers

Hazard: The cord can become brittle near the base of the dryer, posing burn hazards.



This recall involves the Ionic Pro 2000 and 2000W hand-held hair dryers sold under the ISO Beauty and Proliss brand names. The bottom rear of the dryers has "ISO" or "Proliss" printed and model number HD-1820. The dryers were sold in the following colors: black, white, white pearl, peacock, white zebra, pink leopard, blue, and giraffe. These hair dryers were sold online for between \$30 and \$40.

Remedy: Consumers should immediately stop using the recalled hair dryers and contact ISO Beauty for instructions on removing the cord and receiving a refund in the form of a credit for a replacement product from the firm.

Fujitsu Battery Packs

Hazard: The lithium-ion battery packs can overheat, posing burn and fire hazards.

This recall involves Panasonic lithium-ion battery packs for these Fujitsu notebook computers and workstations: CELSIUS H720, LIFEBOOK E752, E733, E743, E753, P702, P772, S710, S752, S762, T732, T734, and T902. Recalled battery pack product numbers are CP556150-03, CP579060-01 and CP629458-03. The product and serial numbers are printed on a white sticker on the battery. Serial numbers included in the recall can be found at <http://www.Fujitsu.com/us> then click “Product Support.”



Remedy: Consumers should immediately stop using the recalled batteries, power off the laptop, remove the battery and follow instructions to obtain a free replacement battery.

Walgreens Pain and Itch Relief Cream



Hazard: The packaging is not child resistant as required by the Poison Prevention Packaging Act.

The recalled Well at Walgreens Pain and Itch Relief Cream tube and packaging are orange with a purple stripe with “Maximum Strength,” “Pain and Itch Relief Cream 4% Lidocaine” and “NET WT 2 OZ (56.7 grams)” printed in white on the front. The Well at Walgreens logo is located on the front upper right corner. The packaging contains the UPC bar code 3 11917 18962 8 on the back.

Remedy: Consumers should immediately place the recalled pain and itch relief cream out of the reach of children and return it to Walgreens for a full refund.

Lenovo ThinkPad XQ Carbon Laptops (5th Gen.)

Hazard: An unfastened screw can damage the battery causing overheating, posing a fire hazard.

This recall involves 14-inch ThinkPad X1 Carbon 5th Generation laptops. They were sold in silver and black. The product name “5th Generation Lenovo ThinkPad X1 Carbon,” the machine type 20HQ, 20HR, 20K3 or 20K4 and the serial number or S/N are printed on the bottom of the laptop. Laptops manufacture dates from 16/12 through 17/10 (for December 2016 through October 2017) are included in the recall. The manufacturing date codes can be found on the bottom of the laptop.



Remedy: Consumers should visit support.lenovo.com/X1C_5GEN_RECALL to see if their laptop is included in the recall and for assistance in locating the nearest authorized repair center for inspection and repair. If the laptop is included in the recall, stop using it immediately.

Tiffany & CO Wheat Leaf Mugs

Hazard: The mugs can crack or break when used with or exposed to hot liquids, posing burn and laceration hazards.

The recall involves the 11-ounce Wheat Leaf crystal glass mugs. The mugs measure about 3.5 inches tall and 3 inches in diameter, with a handle. They are clear with a wheat leaf pattern etched into the glass. The mugs have a blue sticker stating “TIFFANY & CO. Made in Slovenia. CRYSTAL GLASS.” “TIFFANY & CO. 13559” appears on the bottom of the mugs.



Remedy: Consumers should immediately stop using the recalled mugs and contact Tiffany & Co. for a full refund plus a \$100 gift card.

Panasonic 55-Inch LED/LCD Flat Screen TV with Swivel Stand

Hazard: The mounting screws that connect the swivel stand to the television can come loose and cause the television to tip over and fall off the stand unexpectedly, posing serious tip-over and entrapment hazards that can result in injuries or death to children.



This recall involves Panasonic 55-inch, LED/LCD flat screen televisions with a tabletop swivel stand intended for use in hotels, government buildings and schools. The televisions are black and “Panasonic” is printed on the front. The television’s model number is TH055LRU50. The model number is printed on a tag located in the center of the back of the television. The swivel stand is a glossy black color and measures 50.5 inches long by 32 inches tall by 11.1 inches deep. There is a label on the front underside of the base as well as a number etched into the metal.

Remedy: Consumers using the swivel stand should immediately detach it, place the television in a safe location away from children and contact Panasonic for free repair kit.

UGG Hudson Comforters

Hazard: Mold can be present, posing a risk of respiratory or other infections in individuals with compromised immune systems, damaged lungs or an allergy to mold.

This recall involves Hudson comforters by UGG. The polyester comforters were sold in four different solid colors: garnet, navy, gray, and oatmeal, and three sizes: twin, full/queen, and king. See “Sold At” section for affected dates of sale. These comforters were sold by Bed Bath & Beyond for between \$70 and \$110.



Remedy: Consumers should immediately stop using the recalled comforters and return them to Bed Bath & Beyond for a full refund.

Fujifilm Power Adapters

Hazard: The power adapter wall plug can crack, break or detach and remain in the wall and expose live electrical contacts, posing a shock hazard.

This recall involves AC-5VF power adapter wall plugs sold with Fujifilm digital camera models XP90, XP95, XP120, XP125, X-A3 and X-A10. The recalled wall plugs are black and are combined with a power adapter and USB cord that plugs into the adapter. Model number “AC-5VF” is printed on the back of the power adapter. The serial number is printed on the bottom of the camera or under the battery compartment lid. To check your serial number, visit <http://fujifilmusa.com/support/recall/index.html>.



Remedy: Consumers should immediately stop using the recalled power adapter wall plugs and contact Fujifilm for a free replacement. Consumers can continue to charge the camera using the USB cable attached to a computer.

Coldwater Creek Snow Globes

Hazard: Light refraction through the globes can singe or melt items in contact with or in the immediate proximity, posing a fire hazard.



This recall involves two Coldwater Creek snow globes with reindeer or a snowman inside. Style 13826 and model number XC7484, has two white reindeer inside and a brown and cream base. Style 13660 and model number 3WGL120, has a silver snowman inside and a silver base. The Grasslands Road logo and style number appear on separate labels located on the underside of the globe. The style number is the ninth through fourteenth digits printed on the price label.

Remedy: Consumers should immediately stop using the recalled snow globes and contact Coldwater Creek to return the product free of cost for a full refund.

HP Lithium-Ion Batteries

Hazard: The lithium-ion batteries can overheat, posing fire and burn hazards

This recall involves lithium-ion batteries for HP Notebook computers and mobile workstations. The batteries were shipped with or sold as accessories for HP ProBooks (64x G2 and G3 series, 65x G2 and G3 series), HPx360 310 G2, HP Envy m6, HP Pavilion x360, HP 11, HP ZBook (17 G3, 17 G4, and Studio G3) Mobile Workstations. The batteries were also sold as accessories or replacement batteries for the HP ZBook Studio G4 mobile workstation or for any of the products listed above.



Remedy: Consumers should immediately visit www.HP.com/go/batteryprogram2018 to see if their battery is included in the recall and for instructions on how to enable “Battery Safety Mode” if their battery is included in the recall.

DIY Ultra Lounge Bean Bag Chair Covers

Hazard: The zippers on the bean bag chair covers can be opened by children who can then crawl inside, become entrapped, suffocate or choke on the bean bag chair's foam beads.

This recall involves Comfort Research’s Ultra Lounge bean bag chair covers. The natural polyester Sherpa, bean bag chair cover measures 28 inches by 28 inches by 36 inches and has two zippers on the exterior. The covers were sold without foam bead filling in a DIY package. The covers have three sewn-in tags. One tag reads “id COLORS” on the front and “RN48711” on the back. The second tag has the UPC label code “PO#12991” or “PO#13539” on the front.



Remedy: Consumers should immediately take bean bag chairs with the recalled covers away from children and contact Comfort Research for a full refund.

Honda Portable Generator

Hazard: The carburetor can leak gasoline, posing fire and burn hazards.

This recall involves Honda portable gas generators. The recalled portable generators have a red front cover and a black metal frame. The EB2800i has a silver-colored control panel and the EG2800i has a black-colored control panel. The model number is printed on the control panel. The serial number is located on the lower black metal frame toward the rear. The following model numbers, serial numbers and production date ranges are included:



Model	Serial Number Range	Production Date Range
EB2800i	EAAA -1000037 through 1015421	2016/07/31 -2017/09/19
EG2800i	EABA -2000047 through 2020152	2016/07/29 -2017/09/20

Remedy: Consumers should immediately stop using the recalled generators and contact a local authorized Honda Power Equipment dealer to schedule a free inspection and repair.

Bits and Pieces Fiber Optic Tree



Hazard: The AC power adapter can overheat, posing a fire hazard.

This recall involves Bits and Pieces Fiber Optic indoor plug in Christmas tree. The branches have fiber optic light strands that change color. Each tree comes with an AC power adapter that is attached to the gold tone base. The AC power adapter plugs into a standard household outlet. The 18-inch-tall tree item number is 43560 and weighs about three pounds. The 31-inch-tall tree item number is 43559 and weighs about four pounds. The item numbers can be found on the UPC barcode label on the box.

Remedy: Consumers should immediately stop using the recalled power adapters, unplug them from the Christmas Tree and contact Melville for a full refund and free shipping.

Monte Carlo Cyclone Ceiling Fan

Hazard: The brackets connected to the fan blades can break, causing the blades to fall, posing an impact injury hazard.

This recall involves two models of the Monte Carlo “Cyclone” ceiling fans with five blades. The fans are 60 inches wide and have either a Roman Bronze or White finish. The model numbers are 5CY60RB for the Roman Bronze and 5CY60WH for the White finish and can be found on top of the motor housing. The Manufacturer Purchase Order numbers (MPO#) can also be found on top of the motor housing. For the Cyclone model ceiling fan in Roman Bronze finish, they are: 30082259, 30100285, 30103624, 30115763, 30126474, 30128431, 30139761, 30143432 and for the White finish, they are: 2020018, 30082259, 30139815, and 30139829.



Remedy: Consumer should immediately stop using the recalled ceiling fans and contact Monte Carlo to receive a free bracket replacement kit with instructions.

Hunter Contempo Ceiling Fan

Hazard: The owner’s manual instructs consumers to install the light globe incorrectly and the light globe can fall, posing an impact injury hazard.

This recall involves Hunter Contempo ceiling fan models 59176 and 59174. The model number can be found on a label on top of the motor housing. The fan comes with five reversible blades and has a 54-inch blade span. Model 59176 comes with cherry and dark walnut blades. Model 59174 comes with light gray oak and gray walnut blades.



Remedy: Consumers with a recalled Contempo model ceiling fan should check to ensure that the light globe was installed correctly by turning it clockwise until it stops and is resting firmly in place.

Pier 1 Imports Glass Pumpkins

Hazard: The wooden stem on the top of the decorative pumpkin can detach when picked up, causing the glass pumpkin base to fall and break, posing a laceration hazard.



This recall involves Pier 1 Imports' decorative clear glass pumpkins with wooden stem. The glass pumpkins have a hollow glass base with a wooden stem attached to the top and were sold in two sizes, small and medium. The recalled pumpkins have the following SKU numbers: 3202753 for the small pumpkin and 3202766 for the medium pumpkin. The SKU numbers can be found on the price sticker located on the bottom of the product. These pumpkins were sold exclusively by Pier 1 Imports for between \$25 and \$30.

Remedy: Consumers should immediately stop using the recalled pumpkins and return them to their nearest Pier 1 Imports store for a full refund or merchandise credit.

Matrix "Surprise Fountain" Fireworks



Hazard: The recalled fireworks are overloaded with pyrotechnics intended to produce an audible effect, violating the federal regulatory standard for this product.

This recall involves the Jumbo Fireworks "Surprise Fountain." The recalled fireworks were sold individually and have product code JFG4279 printed on the front panel above the cautionary text. The fireworks are small red cylinder devices that measure 3 inches tall by about 1 inch wide. "Jumbo Fireworks," "Surprise Fountain," "Warning" and an image of fountains with happy faces are printed on the front.

Remedy: Consumers should not use the recalled fireworks and return them to the place of purchase for a full refund.

Westinghouse Portable Generators

Hazard: The portable generators can overheat, posing a fire hazard to consumers.

This recall involves Westinghouse iGen2500 and iPro2500 portable inverter generators used to power appliances, cell phones or other electronic devices. The iGen2500 has a bright blue plastic cover and has “Westinghouse iGen2500” printed in white lettering on the side and on the front of the generator. The Westinghouse iPro2500 has a plastic gray cover. “Westinghouse iPro2500” is printed in white lettering on the side and front of the generator. The generators measure about 20 inches long by 18 wide inches by 11 inches tall. They weigh about 49 pounds.



Remedy: Consumers should immediately stop using the recalled generators and contact MWE Investments to arrange for a free repair.

West Elm Table Lamps

Hazard: The electrical wire that runs through the lamps can be cut or fray by the lamp’s adjustable joint, posing a risk of electric shock to consumers.



This recall involves West Elm’s Industrial Task table lamps. The metal lamps have an on/off switch and an adjustable arm that locks at two angles. The head of the lamp has a tension that allows it to swivel to direct light. Some models have a USB port in the base. The lamps were sold in various colors and are about 33 inches tall and measure about 7 inches in diameter at the base. West Elm, the SKU# and the date of manufacture in Letter/YYYY format are printed on a sticker on the underside of the base. Dates of manufacture for the non-USB modes are C/2014 and later. All lamps with a USB port in the base are included in this recall. The SKU

numbers for the recalled lamps are the following: 3967424, 9353603, 9353645, 4638800, 4639352, 4639329, 830703, 830760, 1127851, 1128008, 6379200, 1219963, 8170136, 1127778, 1128040, 1128255, 1128289, and 830737. These lamps were sold exclusively by West Elms for between \$80 and \$130.



Remedy: Consumers should immediately stop using the recalled lamps and return them to West Elm for a full refund, including return shipping.

Natural Solutions Maximum Strength Synodrin Pain Relieving Cream with Lidocaine

Hazard: The packaging is not child resistant as required by the Poison Prevention Packaging Act. The pain-relieving cream contains lidocaine, posing a risk of poisoning to young children.

The recalled Synodrin Lidocaine Maximum Strength Pain Relieving Cream is in a white jar with a blue label with “ Synodrin Lidocaine Maximum Strength 4% Pain Relieving Cream” printed on the front. The jars measure about three inches in diameter, are three inches tall and weigh about 4 ounces. They were sold in a blue box with yellow letters



“Lidocaine” and white letters “Maximum Strength 4% Pain Relieving Cream.” The brand name Synodrin is printed on the jar and the box. The box and jar have UPC code 8 64751 00032 6 printed on the right side. These creams were sold in stores nationwide and online for about \$19.

Remedy: Consumers should immediately place the recalled pain-relieving cream out of the reach of children and contact Natural Solutions for Life to obtain a free replacement cap.



Flos Pendant Light Fixtures

Hazard: The glass diffuser can detach and fall, posing an impact injury hazard.

This recall involves the Flos Romeo Moon model S2 and Romeo Louis II model S2 pendant lamps. The model number is printed on a label on the shade. The lamps have an internal glass diffuser covered by a flared glass or crystal shade that suspends from the ceiling by steel wires. Consumers can tell if their lamp is part of the recall by examining the underside of

the ring holding the glass diffuser. If this piece is plastic only, it is part of the recall.

Remedy: Consumers should avoid walking under the fixtures until they are repaired. Consumers should contact the firm or the place of purchase for a free repair kit that can be installed by consumers.

Libby Bourbon Glasses

Hazard: The glasses can break during normal use, posing a laceration hazard.

This recall involves 8 oz. Bourbon Taster Glasses. The glasses are made of clear, colorless glass and measure about 3 7/8 inches tall. The glasses have one of three logos laser-etched on the bottom of the glass: “Kentucky Bourbon Trail,” “Kentucky Bourbon Trail Craft Tours” or “SIV”. The glasses were sold in boxed sets of four glasses and also sold individually.

Remedy: Consumers should immediately stop using the recalled glasses and return them to the place of purchase for a full refund. Commercial customers should contact Libbey to arrange for a credit, full refund or replacement.





Luminette Privacy Sheer Blinds

Hazard: The cord restraints on the combination wand/cord of the sheer blinds can break, posing a strangulation hazard to children.

This recall involves custom-made Luminette privacy sheer blinds and other branded and generic sheer blinds listed below with the combination wand cord sold in white. The Hunter Douglas logo is printed on the end of the wand of the Luminette brand sheer

blinds. The alternative brand and generic sheers do not have a logo. The cord/wand is unique to this product. The product was also sold under the following other brands and names: Allen + Roth Vertical Sheers; Alta Shadings; Budget Blinds Enlightened Style Shadings; Comfortex Vertical Sheer Shadings; Luxaflex; MyBlinds Shadings; Smith & Noble; Vertical Sheer Shadings by Turnils, Unique Wholesale, United Supply, Century, Oxford House, or Matisse; and Vista Shadings.

Remedy: Consumers should immediately stop using the recalled sheer blinds and contact Hunter Douglas for a free repair kit.

Warehouse Fireworks

Hazard: The recalled fireworks are overloaded with pyrotechnics intended to produce an audible effect, violating the federal regulatory standards for this product. Overloaded fireworks can result in a greater than expected explosion, posing burn and explosion hazards to consumers.

This recall involves “Toxic” artillery rockets, “Boom Box” aerial shells and “Detonator” firecrackers.

Remedy:

Consumers should immediately stop using the recalled fireworks and contact Wholesale Fireworks for a full refund.





Sporting Goods and Recreational Vehicles



Honda Recreation Vehicles

Hazard: An incorrectly installed throttle body can ignite, posing fire and burn hazards to consumers.

This recall involves all model year 2016 through 2017, and some model year 2018 Honda Pioneer 1000 side-by-side vehicles. The recalled vehicles were sold in various colors including: red, blue, green, gray and yellow. The name



“HONDA” is on the front, sides and the rear of the vehicle. The model name Pioneer 1000 is printed on a label located on both sides of the vehicle, near the rear. The serial number (VIN #) is stamped in the frame at the left rear, below the tilt-up bed/seat. The following model numbers and serial number ranges are being recalled: 2016 Pioneer 1000 3P models with VIN range 1HFVE04**G4000001 through 1HFVE04**G4008403; 2016 Pioneer 1000 5P models with VIN range 1HFVE04**G4000001 through 1HFVE04**G4010507; 2017 Pioneer 1000 3P models with VIN range 1HFVE04**H4100001 through 1HFVE04**H4102101; 2017 Pioneer 1000 5P models with VIN range 1HFVE04**H4100001 through 1HFVE04**H4103000; 2018 Pioneer 1000 3P models with VIN range 1HFVE04**J4200001 through 1HFVE04**J4200720; and 2018 Pioneer 1000 5P models with VIN range 1HFVE04**J4200001 through 1HFVE04**J4200780. These vehicles were sold at authorized Honda Powersports dealers nationwide from August 2015 through August 2018 for between \$14,000 and \$22,000.

Remedy: Consumers should immediately stop using the recalled ROVs and contact an authorized Honda Powersports dealer to schedule an appointment for a free inspection and repair.

CFMOTO Recreational Vehicle

Hazard: The throttle can be pushed past the throttle stop and not return to idle position, posing a crash hazard.

This recall involves 2018 ZFORCE 500 Trail, 2018 ZFORCE 800 Trail and 2018 ZFORCE 1000 SSV CFMOTO recreational off-highway vehicles with 500cc to 1000cc, 4-cycle engines. The recalled ZFORCE

vehicles have “CFMOTO” stamped on the front grille, a “CFMOTO” decal on the bottom of the cab frame and a “ZFORCE” decal located on each side of rear box compartment. CFMOTO ZFORCE vehicles were sold in orange, blue, red and gray. These vehicles were sold at CFMOTO dealers nationwide from January 2018 through July 2018 for between \$9,000 and \$14,000.



Remedy: Consumers should immediately stop using the recalled ROVs and contact a CFMOTO dealer to schedule a free repair.

Shimano Lazer Bike Helmets

Hazard: The helmets do not comply with the federal safety standard for bicycle helmets.

This recall involves Shimano’s Lazer-branded helmets, models Blade, Elle, Jade and Magma. They were sold in the following colors: black, black and pink, blue, dark blue, grey and yellow, khaki and orange, titanium, red, yellow, and white. Lazer is printed on the side of the helmet. Model LZB-08 is printed on a sticker inside the helmet. Only XS and S sizes are included in the recall.



Remedy: Consumers should immediately stop using the recalled helmets and contact Shimano for instructions on how to receive a free replacement helmet.



Yvolve Neon One-Wheel Electric Skateboards

Hazard: The tire on the skateboard can deflate, posing a fall hazard.

This recall involves the Neon Nitro 8, a self-balancing, single-wheeled, battery-powered, electric skateboard from Yvolve Sports under the Neon brand. The product is powered by the user placing one foot on the rear and front decks, gaining balance and then shifting their weight backwards or forwards to control the speed. These skateboards were sold at Walmart, Toys “R” Us and online at Amazon.com for about \$500.


Remedy: Consumers should stop using the skateboards immediately and contact Yvolve Sports to receive a new permanent warning label and updated instructions on how to properly inflate the tire.

Merge Metal Playground Climbers

Hazard: The two welded handgrip locations at the top of the climbers can be too large creating a strangulation hazard. A child’s body could become lodged in these openings, posing a strangulation hazard.

This recall involves the Burke Merge Metal Climbers. These climbers are used on play equipment as an attachment that allows children to climb up and access the play structure. The metal climbers were sold in many color combinations with small geometric shaped openings with a platform and two welded handgrips at the top. “Burke” is printed on identification labels that are placed on the exterior of the entire play structure. These were sold as pieces of equipment for public and private use for about \$1,400.

Remedy: Consumers should immediately remove these climbers from use and contact the firm for a free repair kit.





CFMOTO All-Terrain Vehicles

Hazard: The fuel hose can crack and fuel can leak from the vehicle, posing a fire hazard.

This recall involves 2016-2018 CForce 400, 2017-2018 CForce 500S and 2017-2018 CForce 500HO ATVs with 400cc to 500cc, 4-cycle engines. The “CFMOTO” logo is located on the front and rear grille, and a “CForce” decal is on each side of

the fuel tank. CFMOTO CForce vehicles were sold in orange, blue, red and gray. The vehicle identification number (VIN) is located under the seat on the right side, top frame rail. These vehicles were sold at CFMOTO dealers for between \$4,200 and \$6,000.

Remedy: Consumers should immediately stop using the recalled ATVs and contact a CFMOTO dealer to schedule a free repair.

Provata Activity Trackers

Hazard: The activity tracker wristbands can overheat while the user is wearing it or when charging, posing a burn hazard.

This recall involves the Provata activity fitness tracker. The wristbands were given to consumers as a promotional giveaway and feature a digital display, a charging terminal, a heart rate and step detector with Bluetooth technology. They were distributed in three colors: black, blue or mint green. The packaging displays the word “Provata” and “Activity Tracker” printed on the front cover. These trackers were distributed free at wellness events.

Remedy: Consumers should immediately stop wearing or charging the recalled wristbands and contact Provata Health for instructions on how to receive a free replacement wristband.



Polaris Recreational Vehicles



Hazard: The front lower control arms can separate, posing a crash hazard.

The recall involves model year 2018 Polaris Ranger 500, Ranger 570, Ranger EV and Ranger EV LI-ION recreational off-highway vehicles. The Ranger 500 vehicles were sold in red and green. They have “POLARIS” stamped on the front grille, “500” decals on the front fenders, and “Ranger” decals on the rear fenders. The Ranger 570 vehicles were sold in two- and four-seat models in

green, blue, and camo. They have “POLARIS” stamped on the front grille, “570” decals on the front fenders, and “Ranger” decals on the rear fenders. The Ranger EV vehicles were sold in gray and camo. They have “POLARIS” stamped on the front grille and “Ranger” decals on the rear fenders. The Ranger EV LI-ION vehicles were sold in camo. They have “POLARIS” stamped on the front grille and “Ranger” decals on the rear fenders. The Vehicle Identification Number (VIN) and model number may be found on a label inside the left rear wheel well. These vehicles were sold at Polaris dealers nationwide for between \$9,000 and \$12,500.

Remedy: Consumer should immediately stop using the recalled ROVs and contact a Polaris dealer to schedule a free repair.

Polaris RZR Recreational Vehicles

Hazard: In the event of a high-speed rollover, the vehicle’s rollover protection structure (ROPS) can fracture, providing inadequate protection during a rollover.

This recall involves model year 2018 RZR XP Turbo S recreational off-highway vehicles (ROVs) sold in red and blue. The recalled vehicles have “POLARIS” printed





on the front grille, “POLARIS” printed beneath the doors, and “RZR” printed on the rear fenders. The vehicle identification number (VIN) and model number can be found on a label affixed to the vehicle frame in the left front wheel well. Affected model numbers include Z18VEL92BR and Z18VEL92BK. These vehicles were sold at Polaris dealers nationwide for about \$27,500.

Remedy: Consumers should immediately stop using the recalled ROVs and contact a Polaris dealer to schedule a free repair.

Confer In-Pool Step Systems

Hazard: Children’s limbs can become entrapped in the side openings of the step systems, posing a drowning hazard.

This recall involves three models of in-pool step systems with curved steps for in-ground and aboveground pools. The steps and handrails are made of gray and beige plastic. The manufacturing/date code is located on the side walls of each step. Affected models include all #CCX-AG, #CCX-IG, and #CCX-ADD models manufactured from 2013-2018. These step systems were sold at pool supply stores nationwide and online for between \$200 and \$400.

Remedy: Consumers should immediately stop using the recalled pool step systems and contact Confer Plastics for a free repair kit. The repair kit will include additional panels to prevent entrapment and installation instructions.





Polaris ACE and Ranger Recreational Vehicles

Hazard: The front suspension lower ball joint can separate, posing a crash hazard.

This recall involves model year 2017-2018 Polaris ACE 150 and model year 2018 Polaris Ranger 150 recreational off-highway vehicles. The recalled vehicles were sold in red and white. The recalled ACE 150 vehicles have “POLARIS” stamped on the front grille, a “POLARIS” decal on the bottom of the cab frame and an “ACE” decal on the rear fender. The recalled Ranger 150 vehicles have “POLARIS” stamped on the front grille, a “150” decal on the front fender and a “RANGER” decal on the rear fender. The model number is printed on the emissions label on the frame in the right front wheel well. Affected model numbers include A17HAA15A7, A17HAA15B7, A18HAA15B2, A18HZA15B4, and A18HAA15B7. These vehicles were sold at Polaris dealers nationwide for between \$3,800 and \$5,000.

Remedy: Consumers should immediately stop using the recalled ROVs and contact a Polaris dealer to schedule a free repair.

Rollerblade Helmets

Hazard: The helmets fail to meet the federal standard, posing a risk of head injury.

This recall involves Rollerblade-branded Helmets R Us helmets, used in schools’ physical education programs. The recalled helmets are white and Rollerblade is printed on the side in black. They were manufactured from September 2011 through April 2017. Model 16, SK-501N and the manufactured date (in MM/YYYY format) are printed on a label on the inside of the helmet. These helmets were sold nationwide for about \$16.



Remedy: Consumers should immediately stop using the recalled helmets and contact Helmets R Us to receive a free replacement helmet.

Stargaze Camping Chairs

Hazard: The plastic joint supports attached to the legs of the chairs can break, posing a fall hazard.



This recall involves the Stargaze Recliner, Stargaze Recliner Low, and Stargaze Recliner Luxury lifestyle camping chairs. These portable swinging and reclining outdoor chairs have an aluminum frame and black and gray monofilament mesh seat, and weigh between five and seven pounds. They were sold in four colors: birch leaf green, graphite, verdigris (teal) and Sedona (red). They come in a black, padded carrying case, and are used as a portable seat for camping and outdoor activities. The model name is printed on the pocket on the inside right side of the seat. The NEMO name and logo is attached to the back of the seat as a stitched logo. The three manufacturing lots included in this recall are marked with November 2017, December 2017, March 2018 or May 2018 date codes. The date code can be found on the plastic hub located on the inside edge of the leg strut. The date code is in a clock format: The numbers around the circle correspond to the 12 months of the year, the arrow points to the month of manufacture and the numbers on either side of the arrow represent the last two digits of the year. These chairs were sold at retailers nationwide and online for between \$180 and \$200.

Remedy: Consumers should immediately stop using the recalled chairs and contact NEMO Equipment for a free inspection and, if necessary, a free replacement chair.



Can-Am Outlander and Renegade ATVs

Hazard: Fuel can spray from the fuel tank when opening the gas cap, posing a fuel leak and fire hazard.

This recall involves model year 2018 Can-Am Outlander and Renegade all-terrain vehicles sold in a variety of colors. Can-Am and the

model name are printed on the side panels of the vehicles. The vehicle identification number (VIN) is printed on the frame under the seat in the middle and on the frame behind the right front wheel. The following models are included in the recall: OUTLANDER 450, 570 and 650; OUTLANDER 6X6 DPS 650; OUTLANDER 6X6 XT 1000; OUTLANDER DPS 450, 570, 650, 850 and 1000R; OUTLANDER DPS LE 570; OUTLANDER MAX 450 and 570; OUTLANDER MAX DPS 450, 570 and 650; OUTLANDER MAX LTD 1000R; OUTLANDER MAX WIN 650 and 850; OUTLANDER MAX XT 570, 650, 850 and 1000R; OUTLANDER MAX XT LE 650; OUTLANDER MAX XTP 850 and 1000R; OUTLANDER MOS 450, 570 and 1000R; OUTLANDER WIN 650 and 850; OUTLANDER XT 570, 650, 850 and 1000R; OUTLANDER XTP 850 and 1000R; OUTLANDER XXC 1000R; RENEGADE 570, 850 and 1000; and RENEGADE XXC 850 and 1000R. These vehicles were sold at Can-Am dealers nationwide for between \$6,000 and \$16,500.

Remedy: Consumers should immediately stop using the recalled vehicles and contact a BRP Can-Am ATV dealer for a free repair.

L.L.Bean Allagash Fixed Blade Hunting Knife and Sheath

Hazard: The knife blade can cut through the protective leather sheath, posing a laceration hazard.

This recall involves the Allagash fixed blade hunting knife with sheath. The sheath measures 7 inches long by 2 inches wide, is made of brown leather and contains white stitching down one side. The knife blade measures 3.55 inches long by 1 inch wide, is made of stainless steel and is attached to a light brown handle. L.L.Bean is embossed on the brown leather sheath and engraved on the top of the knife blade near handle on one side. The recalled knife with sheath has the product identification number 501794 printed on the green box in which the knife is packaged. These knives were sold by L.L.Bean for about \$90.



Remedy: Consumers should immediately stop using the knife with sheath, and cover and store in a safe area out of the reach of children. Contact L.L.Bean for a free replacement sheath.



Nerf Battle Racer Go-Karts

Hazard: The steering wheel on the go-kart can detach, break or crack while in use, posing a laceration and/or collision hazard to children.

This recall involves the Nerf Battle Racers, a four-wheel pedal powered go-kart for children ages 4 to 10. The wheels are black and orange. It measures approximately 50 inches long by 27 inches high by 24 inches

wide. The model number T91869, and the date of manufacture is printed on a white sticker located on the underside of the seat. Only go-karts with a date of manufacture between 01/2016 and 03/2017 are being recalled. These go-karts were sold for between \$200 and \$300.

Remedy: Consumers should immediately stop using the recalled go-karts and contact Hauck for a new steering wheel.

Polaris Ranger XP Recreational Vehicles

Hazard: The center seat belt bracket can separate from the frame, posing an injury hazard to the riders.

This recall involves model year 2016 and 2017 Polaris Ranger XP recreational off-highway vehicles (ROVs) sold in a variety of colors. The ROVs have “POLARIS” printed on the front grill, “XP” on the front fenders, and “RANGER” on the rear fenders. The vehicle identification number (VIN) is printed on a label on the driver-side frame of the vehicle, between the



cargo box and left rear tire. The following model numbers are included in the recall: R16RTA87A1, R16RTA87A4, R16RTA87A9, R16RTE87A1, R16RTE87A4, R16RTE87AK, R16RTE87AM, R16RTE87AS, R16RTE87AV, R16RTE87A9, R17RTA87A1, R17RTA87A9, R17RTE87A1, R17RTE87A4, R17RVA87A1, R17RTA99A1, R17RVA99A1, R17RVE87A9, R17RTE99AS, R17RTE99AW, R17RTE99AY, R17RTE99A9, R17RVE99A9, R17RVE99AS, R17RVE99AY, R17RTM99AM, and R17RVM99AM. These vehicles were sold at Polaris dealers nationwide for between \$12,000 and \$20,000.

Remedy: Consumers should immediately stop using the recalled ROVs and contact a Polaris dealer to schedule a free inspection and repair.

Polaris Phoenix 200 ATVs

Hazard: The throttle limiter can fail due to damage during shipping, posing a crash hazard.

This recall involves all model year 2014 through 2017 Phoenix 200 all-terrain vehicles. “Polaris” is stamped on the front grill and on the sides of the ATV seats, and “Phoenix 200” is stamped on the side panels. The ATVs were sold in blue and gray. Model numbers A14PB20AF, A15YAP20AF, A16YAP20AF and A17YAP20A8 are included in this recall. The model number is located on the vehicle frame. To check for recalled vehicles by vehicle identification number (VIN) visit www.polaris.com. These vehicles were sold at Polaris dealers nationwide for about \$3,600.



Remedy: Consumers should immediately stop using the recalled ATVs and contact Polaris for instructions on how to inspect for a damaged throttle limiter, and, if damaged, to schedule a free repair.

Can-Am Outlander ATVs

Hazard: The dynamic power steering shaft can break and result in a loss of steering control, posing a crash hazard to consumers.

This recall involves model year 2017 Can-Am Outlander and Outlander Max all-terrain vehicles equipped with a dynamic power steering (DPS) and a 450 or 570 engine. The vehicles were sold in various colors. The model name is printed on the side panels of the vehicles. The vehicle identification number (VIN) is printed on the frame under the seat in the middle and on the frame behind the right front wheel. These vehicles were sold at Can-Am dealers nationwide for between \$6,000 and \$9,750.



Remedy: Consumers should immediately stop using the recalled vehicles and contact a BRP Can-Am ATV dealer for a free repair.

Polaris RZR XP 1000 Recreational Vehicles

Hazard: If the exhaust silencer fatigues and cracks, the heat shield may not manage heat, which may lead to melting of nearby components or fire.

This recall involves Model Year 2014-18 Polaris RZR XP 1000 recreational off-highway vehicles (ROVs). The ROVs have “POLARIS” stamped on the front and back grilles, and “Polaris,” “RZR,” “1000,” & “XP” stickers on the side panels. These vehicles have been sold at Polaris dealers nationwide since 2013.



Remedy: Consumers should immediately stop riding the affected vehicles and contact a Polaris dealer for a free repair.

Honda Recreational Vehicles

Hazard: The muffler can overheat, causing the plastic heat shield to melt or catch fire, posing a fire and burn hazard to consumers.

This recall involves all model year 2016 through 2017, and some model year 2018 Honda Pioneer 1000 Vehicles. The recalled vehicles were sold in various colors including: red, blue, green, gray and yellow. The

name “HONDA” is on the front, sides and the rear of the vehicle. The model name Pioneer 1000 is printed on a label located on both sides of the vehicle, near the rear. The serial number (VIN #) is stamped in the frame at the left rear, below the tilt-up bed/seat. The following model numbers and serial number ranges are being recalled: 2016 Pioneer 1000 3P with VIN 1HFVE04**G4000001 --- 1HFVE04**G4008403, 2016 Pioneer 1000 5P with VIN 1HFVE04**G4000001 --- 1HFVE04**G4010507, 2017 Pioneer 1000 3P with VIN 1HFVE04**H4100001 --- 1HFVE04**H4102101, 2017 Pioneer 1000 5P with VIN 1HFVE04**H4100001 --- 1HFVE04**H4103000, 2018 Pioneer 1000 3P with VIN 1HFVE04**G4200001 --- 1HFVE04**G4203360, and 2018 Pioneer 1000 5P with VIN 1HFVE04**G4200001 --- 1HFVE04**G4207379. These vehicles were sold at authorized Honda dealers nationwide for between \$14,000 and \$22,000.



Remedy: Consumers should immediately stop using the recalled ROVs and contact an authorized Honda Powersports dealer to schedule an appointment for a free inspection and repair.

Louis Garneau Bicycle Helmets

Hazard: The bicycle helmets do not comply with the impact requirements of the federal safety standard for bicycle helmets, posing a risk of head injury.



This recall involves Louis Garneau Course Helmets with model number LG1261 printed on the inside of the helmet. “Garneau,” “Course” and “LG” are printed on both sides of the recalled bicycle helmets. The manufacturer’s date and serial number are printed on a sticker inside the helmet: Lot 2016-09 range 712713 to 712955; lot 2016-09 range 713088 to 713195; lot 2016-09 range 713298 to 713783; lot 2016-09 range 713859 to 713948; lot 2016-09 range 714284 to 714433; lot 2015-11 range 719591 to 719740; lot 2015-09 range 716198 to 716560; lot 2015-09 range 716621 to 717010; and lot 2015-09 range 717122 to 718070.

Remedy: Consumers should immediately stop using the recalled helmets and contact Louis Garneau for instructions on how to receive a free replacement helmet.

Polaris RZR XP 4 Turbo

Hazard: The return fuel line can be improperly secured which can cause fuel to leak, posing a fire hazard.

This recall involves Polaris model year 2018 RZR XP 4 Turbo recreational off-highway vehicle (ROVs) with seating for four. “POLARIS” is printed on the front grill, “DOHC TURBO” and “EPS” on the front fenders, “POLARIS RZR XP” on the rear fenders, “POLARIS” along the bottom edge of the passenger compartment, and “POLARIS” on the rear light assembly. The VIN is printed on the right rear frame of the vehicle.



Remedy: Consumers should immediately stop using the recalled ROVs and contact a Polaris dealer for a free inspection and repair.

Arctic Cat Recreational Off-Highway Vehicles

Hazard: The winch solenoid located under the operator seat can overheat, posing a fire hazard.

This recall involves all 2017 Arctic Cat Wildcat Trail SE (Special Edition) and Wildcat Sport SE ROVs with winch solenoids installed as original equipment and winch accessory kits sold separately for use on

2014 through 2017 Arctic Cat Wildcat Sport and Wildcat Trail ROVs. The ROVs have four wheels, side-by-side seating for two people, and have a black chassis. “Wildcat Trail” or “Wildcat Sport” is printed on each side of the vehicle. In addition, Special Edition ROVs have “SE” printed on each side. These vehicles were sold at Arctic Cat dealers nationwide for about \$17,000. The winch accessory kits were also sold separately for between \$200 and \$600.

Remedy: Consumers should immediately stop using the recalled ROVs and contact Arctic Cat to schedule a free repair.





Toys



INNOCHEER Children’s Musical Instrument Sets

Hazard: Paint on some instruments contains levels of lead that exceed the federal lead paint ban.

This recall involves INNOCHEER children’s musical instruments sets. The 18-piece instrument sets have one xylophone, two mallets, two maracas, one jingle stick, one sleigh bell, four shaker eggs, two finger castanets, one rainbow bell stick, one mini tambourine and one triangle with striker. The instruments set comes inside a clear plastic bag that measures about 8.9 inches by 8.9 inches by 3.2 inches and has a green trim and a yellow zipper and handles. INNOCHEER is printed in green on the front of the bag. These sets were sold on Amazon.com for between \$21 and \$33.



Remedy: Consumers should immediately stop using the recalled instrument sets and carrying case and contact Creative Sto for a full refund.

Green Sprouts Flower Rattle



Hazard: Pieces of the rattle can detach, posing a choking hazard to children.

This recall involves the Green Sprouts brand flower rattle made from wood. The recalled multi-colored rattles are made from natural wood and measure 2.5 inches long by 2.5 inches wide by 4 inches high. Attached to the circular handle are three round wooden balls shaped like flowers, including one that contains a silver metal bell, all attached with an elastic cord. “Green Sprouts,” “Made in Taiwan” and a date code

number (14714 or 21815) are printed on the circular rattle handle. These rattles were sold at Whole Foods Market and other stores as well as online at Amazon.com and other websites for about \$15.

Remedy: Consumers should immediately take the recalled rattles away from children and contact i play for instructions on how to receive a \$50.00 coupon code to redeem toward the purchase of new products and shipping costs.

Mason and Billy Action Dolls

Hazard: The joints on the vinyl dolls can break, creating broken pieces that pose a choking hazard to young children.

This recall involves four styles of Boy Story action dolls. They include the Mason and Billy Action Dolls, and the Mason and Billy HeForShe Special Edition Action Dolls. The recalled dolls are vinyl and measure 4 inches long by 7 inches wide by 18 inches high. They also came with outfits consisting of a button-up shirt, white t-shirt and jeans. Boy Story LLC is stamped on the left



foot of each doll. These dolls were sold online at biddleandbob.com and at specialty retailers for about \$100.

Remedy: Consumers should immediately take the recalled dolls away from children and contact Boy Story LLC for instructions on how to receive a full refund of the purchase price.

BSN SPORTS Rubber Critter Toys

Hazard: The orange and yellow surface paint on the rubber critter toys contains levels of lead that exceed the federal lead paint ban.



This recall involves all rubber critter toys sold in various colors and animal shapes including octopus, alligators, chickens, frogs, pigs, penguins and cows. The toys were sold individually and in sets ranging from two to 24 rubber critters in catalogs and online for \$10 per toy or up to \$145 for a set.

Remedy: Consumers should immediately take the recalled rubber critter toys away from children and contact BSN SPORTS for a merchandise credit.

Pull-Back Speedy Jets

Hazard: The rubber tires can separate from the wheels, posing a choking hazard for young children.

The Pull-Back Speedy Jet is a wooden toy airplane with a blue painted body, natural wood wings and plastic wheels with black rubber tires. The toy has a pull-back feature that propels the plane forward. The model number and lot code are printed on the bottom of the plane. The recall only includes toy planes with lot

code 155400 EJ. These jets were sold at retailers nationwide for about \$8.



Remedy: Consumers should immediately take the recalled toy away from children and return it to the store where purchased or contact Manhattan Toy for a full refund.

Munchkin Waterpede Bath Toy

Hazard: The bath toy can break apart exposing small parts, posing a choking hazard to young children.

This recall involves Munchkin’s Waterpede bath toys. The one piece multi-colored Centipede -shaped toy allows water to be scooped from the top, and flows through the chambers of bottom. The bath toy is 100% plastic and is for children six months and up. These bath toys were sold at retailers nationwide and online for between \$5 and \$7.

Remedy: Consumers should immediately take the bath toy away from young children and contact Munchkin for a free replacement bath toy of comparable value.



Petit Collage Wooden Xylophones

Hazard: The ball on the end of the toy xylophone beater stick can separate, posing a choking hazard to young children.

This recall involves Petit Collage musical jumbo wooden xylophones. They are musical instrument toys for children. The recalled toy xylophone has a wooden base shaped like the profile of an elephant with five different colored metal keys and a wooden beater stick with a red wooden ball attached to one end. “Petit Collage” and “TT.1902.0617” are printed on the bottom back of the xylophone.



Only xylophones with this letter/number combination are included in the recall.

Remedy: Consumers should immediately take the recalled toy xylophone beater sticks away from children, stop using them and contact Wild & Wolf for a free replacement beater stick.

My First Porsche Wooden Cars

Hazard: The wheels and axles can detach from the wooden toy car, posing a choking hazard.



This recall involves a blue wooden toy Porsche car with tan wheels. The Porsche crest is printed on the front of the recalled toy cars. "PORSCHE" is printed on both sides of the recalled toy cars. The underside of the toy has "BAJO" and a lot number printed on it. The following lot numbers are included in this recall: 011215, 020916, 031017, 031114, 031116, 040116, 040416, 040516, 041217, 051015, 061117, and 090915. These cars were sold by Porsche for about \$25.

Remedy: Consumers should immediately stop using the recalled toy cars, take them away from young children and contact a local authorized Porsche dealer to return the recalled toy car and receive a full refund.

Colorations Extra-Large Crayons



Hazard: The red crayons in the multi-color sets can contain glass, posing a laceration hazard to the user.

This recall involves Colorations brand 200 extra-large crayon sets, including 25 red crayons. The crayons were packaged in a purple and yellow box with the Colorations logo printed on the box. These sets were sold online for about \$36.

Remedy: Consumers should immediately stop using the recalled crayons and contact Discount School Supply to obtain a free full replacement set.

Creatology Spin Art Kits

Hazard: The battery compartment in the spin art kit can overheat.

This recall involves spin art kits sold under the Michaels private brand Creatology. The 34-piece kit includes one battery-operated spin art wheel with cover, paint, paint brushes, and paper. The recalled kits are blue and have SKU number 197861 and one of the following UPC codes printed on the barcode on the box: 042409093252, 042409930601, 042409093115, 042409093061, 042409931141, 069545093113, and 400100663486.



Remedy: Consumers should immediately take the recalled spin art kits away from children, stop using them and return them to any Michaels store for a full refund.

Creatology Pottery Wheel Kits

Hazard: The battery compartment in the pottery wheel kit can overheat.

This recall involves pottery wheel kits sold under the Michaels private brand Creatology. The 16-piece kit includes a battery-operated pottery wheel, 2 bags of clay, 4 molding tools, 6 paints, 2 paint brushes, and a sponge. The recalled pottery wheel kits are blue and have SKU number 078859 and one of the following UPC



codes printed on the barcode on the back of the box: 0400100663462, 0042409006603, 0042409006702, 0042409006757, 0069545670017, and 0886946767692.

Remedy: Consumers should immediately take the recalled pottery kits away from children, stop using them and return them to any Michaels store for a full refund.

Playtime Pals Pop-Up Tents

Hazard: The fiberglass rod that supports the tent can break, splinter and become sharp, posing a laceration hazard to consumers.



This recall involves the Playtime Pals Pop-Up Hideaway Hut animal themed children's tent. The tent has four animal themes: hippo (pink), dog (brown), shark (blue) and tiger (orange). All have a fiberglass rod that springs to deploy the tent to shape and provides the support for the nylon shell. These tents were sold exclusively at Home Depot stores nationwide for about \$13.

Remedy: Consumers should immediately stop using the recalled tents and return them to Home Depot for a full refund or store credit.

Radio Flyer eWagons

Hazard: Improper wiring can activate the wagon's motor unintentionally..

This recall involves Radio Flyer's eWagon children's battery-operated electric wagons. When force is applied to the wagon's electric handle, the motor activates to power the wagon. The foldable wagon is constructed of red and gray fabric and



a steel frame and measures about 41 inches long, 25 inches wide, and 42 inches tall. Only wagons with model number 3912/3912A are included in this recall. The model number can be found on the handle warning label located near the pivoting joint.

Remedy: Consumers should immediately stop using the recalled wagons and contact Radio Flyer for a full refund.

Clay Craft Kits

Hazard: Mold can be present in the clay, posing a risk of respiratory or other infections in individuals with compromised immune systems, damaged lungs or an allergy to mold.

This recall involves “totally me!” clay craft kits. Model number AD11244 is printed on the bottom of the box. The “totally me!” logo is printed on the front of the craft kit box. These kits were sold at Toy “R” Us stores and online for about \$10.



Remedy: Consumers should immediately stop using the recalled craft kits.

Vtech Shake & Sing Elephant Rattles

Hazard: The ears on the elephant rattles can break off, posing a choking hazard to young children.

This recall involves Vtech Shake and Sing Elephant rattle with model number 80-184800. The rattle has a purple elephant with yellow and blue ears at one end and a black and white plastic teething ring at the other end. VTech is stamped on the elephant. The rattle is about seven inches long and the number 1848 is printed on the back of the rattle adjacent to the battery door. The rattle sings when a button is switched on. These rattles were sold in stores nationwide and online for about \$8.



Remedy: Consumers should immediately stop using the recalled rattles and contact VTech for a full refund or credit for a replacement product.

Pokemon Fidget Spinner Keychains

Hazard: The center post on the fidget spinner can become loose or fall out, posing a choking hazard.

This recall involves Pokemon fidget spinner keychains. The keychains have a silver metal key ring with a metal bar attached to it with a Pokemon-themed fidget spinner on the end of the metal bar. The fidget spinner is red and white in the center and yellow around the outside. They measure about ½ inch high by 2 ½ inches wide by 4 ½ inches long.

Remedy: Consumers should immediately stop using the recalled keychains and contact Fashion Accessory Bazaar for instructions on how to receive a full refund.



Related Resources

Florida Department of Agriculture and Consumer Services – www.FreshFromFlorida.com

Provides information about Florida’s agriculture industry as well as charities registered to solicit funds in Florida



Florida Department of Health – www.FloridaHealth.gov

Provides information about meat, poultry, and other recalls that might affect Floridians



U.S. Consumer Product Safety Commission – www.CPSC.gov

Provides a comprehensive list of items recalled by their manufacturers



U.S. Department of Agriculture – www.USDA.gov

Provides information about meat and poultry recalls, food security, and health tips



U.S. Food and Drug Administration – www.FDA.gov

Provides information on food, pet food, drug, and medical equipment recalls



Better Business Bureau – www.BBB.org

Provides information on legitimacy of charities and other organizations and businesses





PL-01 The Capitol
Tallahassee, Florida 32399-1050
(850) 414-3300
www.myfloridalegal.com